NAME   Steel S.S. "VENEZUELA" ex   Rpt. Nwc.   74075)
        "WESTMINSTER ABBEY".   Bmn.   No. 74075a)
                                                         505

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Survey

Rule Dimensions ..   412' x 50.5' x 31.5' to Upper Dk.
                        39.5' to Bridge Deck.
Scantling Nos.   ..   82 & 33784.

Proportions   .. ..   Length = 13.08 depths to Upper Dk.
                                 10.43 depths to Bridge Dk.

This vessel was built at Hamburg in 1906 and classed with

the Germanischer Lloyd.

Plans submitted by the Newcastle Surveyors were examined and

the vessel approved for the class 100 A.1., subject to the stream

chain or steel wire, towline hawsers and warps being supplied in

accordance with the rules.

The survey for classification was completed at Bremen, from

which port reports have now been received. The vessel has been

examined in dry dock, the requirements of Section 48 complied with,

a 2nd.S.S.No.3 carried out, alterations made in accordance with the

approved plans, and repairs effected on account of damage, and wear

and tear. The equipment of steel wires supplied is equivalent to

that required by the rules.

It is submitted the vessel appears worthy to be classed:-

100 A.1. (Steel.)

2 Dks. (Steel u Teaks.) & Webframes, "Well Dk."

Cell DB. 384'. l082t

FK. 7 BH. Cem. Lloyd's A.& C.P.   P & B 263', F60'.

Date of build 1906.
8.21 Ham.
S.S.Ham. 2nd.No.3-8.21.

to be DRILLED when vessel
rs old, or at next special 3 side stringers are fitted and not 2 as stated
survey thereafter   It is concluded the requirements of Sec 48 of the Rules have been
                    complied with but the Surveyors should be requested to state if this is so

15. 8. 21.

WS10-0044