WRECK BOX No. 69 Top

(Received at London Office 1UE APR 15 1919) No. 4298.

Rpt. 8.

REPORT of SURVEY for REPAIRS, &c.

WRECK BOX No. 69 (Top)

Date of writing Report 14-4-1919 When handed in at Local Office 14-4-1919 Port of Manchester.

No. in Reg. Book. 331. Survey held at Manchester Date, First Survey 20-3-19 Last Survey 10-4-1919 (No. of Visits Eight.)

on the Wood, ~~Iron or Steel~~. S.S. War Eclensaw Master W. KIRNAHAM

Built at New Westminster B.C. By whom New Westminster Constr. Co When 1918 (YEAR) 6 (MONTH)

TONNAGE:— GROSS 2344 UNDER DK. 1752 NET 1443

Owners Shipping Controller Port belonging to New Westminster B.C.

Owners' Address J. Cook Sons Ltd.
(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Mch. Dry Dock Destined Voyage Gibraltar.

WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 74 Port Liv

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠ 12 A.1. 12.18		X LMC 11.18
~~(Class Contemplated)~~ salted specially treated W.T.B.		

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking and alterations.

Vessel placed in drydock bottom and rudder recorded. Several outside planking butts on port and stbd. sides, chiefly amidships and at sternpost, recaulked. A graving piece has been fitted in defective plank on port side fwd. One rudder post gudgeon resecured. The deep tank has been dispensed with and the after bulkhead and fore & aft. divisional bulkhead of same have been removed. No alterations made to hatches or hatch beams.

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks: Good
Caulking of Decks: "
Waterways: "
Coamings: "
Beams & Fastenings: "
Outside Plating: ✓
Caulking of ditto: ✓
Rivets: ✓
Breasthooks & Crutches: ✓
Transoms: ✓
Frames: ✓
Reverse Frames: ✓
Floors: ✓
Keelsons: Not Exd.

Stringers: Good
Inner Bottom Plating: –
State if Tanks have been examined inside: ✓
State if Tanks now tested: ✓
Bulkheads: not exd.
Ceiling: ✓
Cement or Asphalt (State which.): ✓
Rudder: Good
Steering gear and its connections: "
Windlass: "
Have Pumps now been examined and found efficient? Not Exd.
Have Sluice Valves now been examined and found efficient? Not Exd.
Have Watertight Doors now been examined and found efficient? Not Exd.

Dblng. Plates under Sounding Pipes: ✓
Engine Room Skylights: Good
Coal Bunkers, Open'gs, Lids, &c.: "
Scuppers: ✓
Cargo Hatchways: Good
Hatches: "
Planking of Wood Vessels: Good
Caulking ditto: "
Treenails ditto: "
Breasthooks & Stemson ditto: "
Transoms, Pointers, & Crutches ditto: "
Timbers of Frame at openings ditto: Not Exd.
Ditto ditto at other places ditto: "
Stringers, Clamps & Shelfs ditto: "
Salting (State if examined.) ditto: "

Copper, ~~or Y.M.~~ of Wood Vessels (State if on Bottom) When put on, Month ~~Year~~
Boats: Good
Masts, Yards, &c.: "
Condition, how ascertained: From Mk.
(State if wedges removed): ✓
Sails:
Equipment letter:
Anchors, No. of: 3 B. 1 S. 1 K.
Cables (State if now ranged): No.
" length (on board): Stated size
" Rule length: Complete size.
Hawser & Warps: Sufficient
Standing & Running Rigging: Good.

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of *ss No.* 1–15 and ptND15, &c."

This vessel, so far as seen is in an efficient condition and eligible in my opinion to remain as classed with record of Survey 4-19.

Survey Fee (per Section 28)	£ : :	Fees applied for, 14-4-1919.
~~Special Damage~~ Repair Fee (if any) (per Sec. 29)	£ 2 : 2 : 0	Received by me, 22-4-19
Travelling Expenses (if chargeable)	£ : :	
Second Surveyor's Fee (if any)	£ : :	

A. Campbell
Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. 9 MAY 1919 FRI. 16 MAY 1919

Character Assigned 12 A1. Subject B.S. 4.19 Subject

Is Certificate required? If so, to be sent to

10m.9.17.—Transfer Ink.
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

© 2021 Lloyd's Register Foundation
WS67-0003