Rpt. 8.

(Received at London Office 7 OCT 1932) No. 14740

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 3-10 1932 When handed in at Local Office 3-10 1932 Port of MIDDLESBROUGH.

No. in Reg. Book. 59949 Survey held at SOUTHBANK, MIDDLESBRO on the ~~Wood, Iron or~~ Steel SC. SR. "CITY OF ALEXANDRIA" (EX "RIO PARDO" EX DALMATIA) Date, First Survey 29-9-32 Last Survey 30-9 1932 (No. of Visits 2)

TONNAGE — GROSS 4697. UNDER DK. 3585 NET 2866

~~Built~~ at WESERMÜNDE-G By whom U.C. TECKLENBORG A.G. When 1905 (YEAR. MONTH.)

Owners ELLERMAN LINES L^D Owners' Address (if not already recorded in Appendix to Register Book).

~~Managers~~ ELLERMAN & BUCKNALL S.S. C^O L^D Port belonging to LIVERPOOL

Surveyed Afloat or in Dry Dock? DRY DK. Name of Dock SMITHS DOCK SOUTHBANK. Destined Voyage

WB=CellDBorDBa ... feet; uE&B ... feet; f ... feet
total capacity ... tons. FPT ... tons; APT ... tons; MT ... feet ... tons.

N.B.—All alterations in the existing records should be underlined.

...sel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides ...mined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ...he inner bottom plating, especially in the boiler space.

...port, No. 514 Port Krk.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A1. 9-30		B.S. 3-30
S.S. LIV. N° 3. 1-21		L.M.C. 5-29.
S.S. N.N.C. N° 2-29		C.L. 9-29

Society's Freeboard (if assigned) as painted on Ship and now verified 4 ft. 3¼ ins. CONVENTION FREEBOARD.

...eys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the ...airs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs ...f Damage (the cause of which must be stated) should be separated from Repairs due to other causes; ...eing detailed in the body of the report, should be summarised in the form shown below. Whenever the ...of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ...his form. State also the dates and initials of any letters respecting this case.

...s where the Surveyor has not made a special damage report he is required to state whether he ...services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AS PER RULE, FOR CONDITION.

NOW DONE Vessel placed in dry dock. ...l. bottom, rudder, stern frame and stern, cleaned, ...mined, was placed in good condition. afterwards ...nted.

...IRS. Twelve shell rivets renewed, seam of shell ...te in way of butt port side electro welded ...one port. The shackle pin of port side chain ...e renewed.

...MAGE REPAIRS :—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
... Faired or Repaired								
...aired in place								

...ON OF THE

... GOOD	State if Tanks have been examined inside ✓	Dblng. Plates under Sounding Pipes ✓	~~Copper~~, or Y.M. of Wood Vessels (State if on Felt). When put on, Month ... Year
... "	State if Tanks now tested ✓	Engine Room Skylights GOOD	Boats GOOD
... "	Bulkheads ✓	Coal Bunkers, Open'gs, Lids, &c. "	Masts, Yards, &c. "
... ✓	Ceiling ✓	Scuppers "	Condition, how ascertained FROM DK.
... GOOD	Cement or Asphalt (State which.) ✓	Cargo Hatchways "	(State if wedges removed) ✓
... ✓	Rudder GOOD	Hatches "	Sails ✓
... ✓	Steering gear and its connections "	Planking of Wood Vessels	Equipment letter W
... ✓	Windlass "	Caulking ditto	Anchors, No. of 3 B. 1 S. 1 K.
... ✓	Have Pumps now been examined and found efficient? ✓	Treenails ditto	Cables (State if now ranged) YES
... ✓	Have Sluice Valves now been examined and found efficient? ✓	Breasthooks & Stemson ditto	" length 270 FMS. size 1 29/32
... ✓	Have Watertight Doors now been examined and found efficient? ✓	Transoms, Pointers, & Crutches ditto	" Rule length (on board) " size 2¼
... ✓	Have Ventilators and their Coamings been examined and found efficient? YES	Timbers of Frame at openings ditto	Hawser & Warps GOOD
... ✓		Ditto ditto at other places ditto	Standing and Running Rigging "
		Stringers, Clamps & Shelfs ditto	
		Salting (State if examined.) ditto	

...bservations, Opinion as to Class, Recommendation, &c.:—

...learly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon ...this, for example:—"...to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of ...or "to remain as classed and to have record of survey, 1,24, and the notations of *ss No.* 1–24 and ptND24, &c."

...Vessel is in good condition and eligible in ...my opinion to remain as classed in the Registe... ...book and to have record of survey 9.32.

...y Fee (*per Section 29*) ... £ :

...al Damage or Repair Fee (if any) (*per Sec. 29*) ... £ :

Travelling Expenses (if chargeable) ... £ :

Second Surveyor's Fee (if any) ... £ :

Fees applied for, ... 19...

Received by me. ... 19...

Jas. Crichton
Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. 14 OCT. 1932

Character Assigned 100A1

S10.32 BS. 10.32

Is Certificate required? If so, to be sent to

© 2020 Lloyd's Register Foundation

W601-0128