Rt. 8.

29785

(Received at London Office WED. 20 APR 1921) No. 28075

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report ..... 19... When handed in at Local Office 19 APR 1921 Port of Sunderland

No. in Reg. Book not yet in R.B.

Survey held at Sunderland. Date, First Survey 2 Mar. Last Survey 13 April 1921

on the ~~Wood, Iron or~~ Steel Screw Steamer "TIDAL." (No. of Visits) Master not appointed

TONNAGE:—

GROSS .....

UNDER DK. .....

NET 199

Built at Lowestoft. By whom Colby Bros When YEAR 1921 MONTH 4.

Owners ✓ Port belonging to ✓

Owners' Address (if not already recorded in Appendix to Register Book).

Surveyed Afloat ~~or in Dry Dock~~? Yes. Name of ~~Dock~~ River Wear Destined Voyage ✓

WB=CellDBorDBa ..... feet; uE&B ..... feet; f ..... feet;
total capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. ..... Port .....

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case. .....

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠ 100A.1. (Class contemplated)		

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Survey for Classification as per the Secretary's letter dated 28th February 1921.

Engine and Boiler Casings now rivetted, Loose part of poop and upper decks fitted, rivetted, caulked, tested, examined and found to be satisfactory. Forward machinery space bulkhead tested, and found to be watertight, Sand pump deck connection on port side removed, refitted, tested, found to be watertight.
Steering Gear (hand and steam) Winches, Capstan, and Windlass tried and found to be in working order, deck in way of these examined while the above were running and found to be satisfactory.

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks .....
Caulking of Decks .....
Waterways .....
Coamings .....
Beams & Fastenings .....
Outside Plating .....
Caulking of ditto .....
Rivets .....
Breasthooks & Crutches .....
Transoms .....
Frames .....
Reverse Frames .....
Floors .....
Keelsons .....

Stringers .....
Inner Bottom Plating .....
State if Tanks have been examined inside .....
State if Tanks now tested .....
Bulkheads .....
Ceiling .....
Cement or Asphalt (State which.) .....
Rudder .....
Steering gear and its connections .....
Windlass .....
Have Pumps now been examined and found efficient? .....
Have Sluice Valves now been examined and found efficient? .....
Have Watertight Doors now been examined and found efficient? .....

Ceiling. Plates under Sounding Pipes .....
Engine Room Skylights .....
Coal Bunkers, Open'gs, Lids, &c. .....
Scuppers .....
Cargo Hatchways .....
Hatches .....
Planking of Wood Vessels .....
Caulking ditto .....
Treenails ditto .....
Breasthooks & Stemson ditto .....
Transoms, Pointers, & Crutches ditto .....
Timbers of Frame at openings ditto .....
Ditto ditto at other places ditto .....
Stringers, Clamps & Shelfs ditto .....
Salting (State if examined.) ditto .....

Copper, or Y.M. of Wood Vessels ..... (State if on Felt.)
When put on, Month ..... Year .....
Boats .....
Masts, Yards, &c. .....
Condition, how ascertained ..... (State if wedges removed)
Sails .....
Equipment letter .....
Anchors, No. of .....
Cables (State if now ranged) .....
,, length ..... size .....
,, Rule length (on board) ..... size .....
Hawser & Warps .....
Standing & Running Rigging .....

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of *ss No.* 1-15 and ptND15, &c."

The above work has now been carried out satisfactorily, and the vessel is, in my opinion, eligible for the class contemplated.

Survey Fee (per Section 28) ..... £ : :
Special Damage or Repair Fee (if any) (per Sec. 29) ..... £ : :
Travelling Expenses (if chargeable) ..... £ : :
Second Surveyor's Fee (if any) ..... £ : :

Fees applied for, ... 19.....
Received by me, ... 19.....

TUE MAY 31 1921

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned 100A1 Cargo hatches not fitted

Surveyors are requested not to write on or below the space for Committee's Minute.)

If Certificate required? If so, to be sent to

© 2021 Lloyd's Register Foundation

W717-0093