F.E.

...ed by Chief Ship Surveyor 20.7.05 Received from Chief Ship Surveyor

...SEL'S NAME Stl. S.S. "Sunnyside" Rpt. Hull No. 17001

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	1/20"	Proportions
Spar Sheerstrake . .	✓	✓
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle).	Ordinary, increased to compensate for omission of reverse frames.	

Ceiling has been omitted from the trunk top except along the bilges, and the trunk top increased in thickness at request of Owner, per letter attached.

other aspects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A 1 ("Steel") as recommended.

✠ 100 A 1 ("Steel")

1 DR (Stl) Well Deck.

W. B = Cell DB f 79' 89t FPT 37t

FK 3BH Cell. Lloyds' A+CP Q 86' B 12' F22' Mchy Aft.

C.N.S. 20/7/05

The Surveyor should be requested to state the tests for the 2 3/4" and 1 3/4" steel wires omitted from his report.

C.N.S. W758-0074

© 2020 Lloyd's Register Foundation

...ARS, In 'tween Decks, Size and Spacing			✓					,, Deck, Material and thickness P. Pine	3		3		
,, Hold ,, ,,	2 5/8	42			2 5/8	42		Forecastle Deck Stringer Plate, brdth & thcknss	21	6	21	6	
Quarter, 'tween Dks., ,, ,,			✓					,, Angle on ditto	3 x 3	6	3 x 3	6	