above Crown of ... 18.39
Engine Room ... 4315.31
NAGE FOR FEES.. 1434.87
Engine Room

Stern post ...
2nd Number ... 38937.96
Proportions—Breadth to Length ... 12.93

Managers (Where necessary to be entered in Reg. Book.)
Residence Leadenhall Street, London

(2m,7,6.)

1.

Sent to Chief Surveyors 22.8.06 Received from Chief Surveyors

VESSEL'S NAME Str. S.S. "Arrino" Report No.

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

*Nature of Survey* *When due*

This vessel was stated in Lloyd's Index of the 16th August to have grounded in the River Clyde and to afterwards have refloated, and that she would dry dock for examination.

The Glasgow Surveyors were written to and requested to state whether the vessel had been placed in dry dock and if so whether an opportunity had been afforded them to make a careful examination of her, and with what result.

The Surveyors state in reply that the vessel was placed in dry dock on the Evening of the day upon which she was refloated and was undocked early the following morning. No intimation was received by them of the vessel being placed in dry dock, and no examination was made of her by the Surveyors to this Society. The Builders and Owners' Representative however state that no damage was sustained. The vessel after running her steam trials on the 14th August proceeded to Antwerp where it was arranged by the Builders that certain work which remained to be done to complete the survey for classification would be attended to, and the Antwerp Surveyors were advised.

The first entry report of the vessel has not yet been received.

W969-0033

© 2020 Lloyd's Register Foundation

C.D. 22/8/06 22/8/06

Fore Body, No. and spacing
,, ,, brdth. & thickness
,, No. of Side Stringers ,, ,,
,, Angle on ditto
,, Tie Plates
,, Deck. Material and thickness
STIFFENERS. Number. Single or