

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

MON 22 NOV 1897

Date of writing Report.	19. When handed in at Local Office	20. 11. 1897 Port of BARRY,	
No. in Reg. Book.	Survey held at BARRY,	Date, First Survey 8 Nov. Last Survey	
125 on the Machinery of the Wood, Iron or Steel ss	Strathleven	10 Nov. 1897	
Tonnage Gross 2436		Master (No. of Visits) Moor 3	
Net 1588	Vessel built at Pt. Glasgow By whom Blackwood & Gordon When 1875-11	YEAR. MONTH.	
Registered Horse Power 232	Engines made at Glasgow When 1875 Boilers, when made (Main) 1889 (Donkey) 1884		
No. of Main Boilers 2	Owners Burrell & Son Port Glasgow Voyage		
No. of Donkey Boilers 1	If Surveyed Afloat or in Dry Dock (State name of Dock.) Commercial	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
Steam Pressure— in Main Boilers 160		CHARACTER. Date for Special Survey, Date of last Survey and of Periodical Surveys.	
in Donkey Boilers 54		Years Ago now existing.	Machinery and Boiler Survey (including date of R.S., if any).

Last Survey No. Port

## Particulars of Examination and Repairs (if any) of damage.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER. Date for Special Survey, Date of last Survey and of Periodical Surveys.	Years Ago now existing.	Machinery and Boiler Survey (including date of R.S., if any).
1100 ft 3.97		1 NB 10.89
0.2m 3-10.89		LMC 9.93
0.2m 1-94		BS 7.97

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

Yes If spare propeller shaft fitted, state whether new? New spare shaft

State the distance between lignum vite of stern bush and top of after bearing of screw shaft?

Now rewooded.

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

On account of stranding in Lucy Canal, and heavy weather. See copy of bare Rep: attached. Vessel placed in dry dock, propeller taken off tail shaft drawn examined found fractured, stern bush rewooded, new spare shaft fitted, in place stops bell. New coupling bolts fitted to after coupling, & new bolt stays to guard ring & stern gland. Shafting pumps sea cocks and condenser examined.

The Superintendent desires the examination of the tail shaft & seacock to be considered as part of the I.S.P. no 2 due 10-97.  
To complete the survey all the machinery to be examined except tail shaft & seacock.

## General Observations, Opinion, and Recommendation:— The machinery of the

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, R.S. 0.05, B.C.H.S. 0.05 or L.M.C. 0.05, 140 lb., F.D., &c.)

Vessel is now in good condition and in my opinion eligible to remain as classed.

Fee or Registration Fee (per Sec. 27) £ 1.00  
Survey Fee (per Section 28) £ 2.20  
Official Damage Fee (per Section 28) £ 1.18.  
Rolling Expenses (if chargeable) £ 1.00  
Note  
Date if Certificate is required

Fees applied for  
20.11.1897  
Received by me,  
25/11/97

Henry S. Fisher  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.  
TUES, 21 MAR 1898  
TUES, 12 JUL 1898  
TUES, 28 MAY 1899  
© 2018

Committee's Minute TUES, 23 NOV 1897

TUES, 10 MAY 1898

TUES, 12 JUL 1898

TUES, 28 MAY 1899

Signed

Deferred

Lloyd's Register  
Foundation

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

1st/12 day 1997 inspection not station  
Sew Shipy Grand公主 (due to change  
by providing Hong Kong vented) now  
unvent system had worked in  
connection with

It is submitted that  
this vessel is eligible to  
remain as CLASSED  
to the order as per 1st/12/97

and due

22/11/97

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2018  
Lloyd's Register  
Foundation