

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 18 AUG 1927)

Date of writing Report 17 AUG 1927 When handed in at Local Office 17 AUG 1927 Port of HULL

No. in y. Book. Survey held at Hull Date, First Survey † Last Survey 10 Aug, 1927
(No. of Visits)

7661 on the Machinery of the Wood, Iron or Steel Sc. MR LIZZIE & ANNIE

Tonnage { Gross 119
 Net 65 Vessel built at North Shields By whom J. Softley & Sons When 1877-6
 Nominal Horse Power { 27 Engines made at Newbury By whom Plenty & Sons When 1913
 of Main Boilers { Boilers, when made (Main) (Donkey)
 of Donkey Boilers
 Main Pressure—Main Boilers
 Donkey Boilers

Owners G. F. Birch & Sons (1919) Ltd. Owners' Address _____
 Managers _____ (if not already recorded by Appendix to Register Book).
 Port Hull Voyage _____
 If Surveyed Afloat or in Dry Dock Yes, Drypool D.D. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Previous Report No. _____ Port _____

Particulars of Examination and Repairs (if any) Condition.

Special Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and the details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he has rendered his services for this purpose, and why they were declined

Has a special damage report been made by anyone else? If so, by whom?

Has the Surveyor personally gone inside each Main Boiler separately and made a thorough examination at this time?

Has the Surveyor personally gone inside each Donkey Boiler separately and made a thorough examination at this time?

Where a special examination has not been done, state for what reasons?

Where parts of the Boilers could not be thus thoroughly examined?

Where special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Has the Surveyor examined the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Has the Surveyor examined the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Has the Surveyor examined all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boiler?

Has the Surveyor examined the drain plugs of the Main Boilers? and of the Donkey Boiler?

Has the Surveyor examined all the mountings of the Main Boilers? and of the Donkey Boiler?

Has the shaft now been drawn and examined? Yes Is it fitted with continuous liner? No Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the shaft now been changed? No If so, state reasons _____

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the clearance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft?

Where the examination is not complete, state what arrangements have been made for its completion and what remains to be done?

done. Vessel placed in dry dock, propeller & screw shaft examined found to be in good condition. Connections examined and found in good condition. no. Screw shaft drawn in. Stem bush (cast iron) renewed, & screw shaft skimmed up.

Observations, Opinion, and Recommendation:— The machinery of this vessel as now seen is in good and efficient condition & eligible in my opinion to remain as classed with fresh record of T.S. 8, 27.

Repair Fee (if any) _____
 Received by me, _____
 (if chargeable)

John K. Williams
Engineer Surveyor to Lloyd's Register of Shipping.

Minute TUES, 23 AUG 1927
As now

Insert Character of Ship and Machinery precisely as in the Register Book.

N.B. - If this Report is copied by copying Press, special care must be taken that the copying paper is not so much damaged as to spread the ink, or to cause it to show through to the other side.

Steel bush renewed

Steel shaft examined.

*It is submitted that
this vessel is eligible to
remain as CLASSED.*

5.8.27

[Signature]

20/5/27

*The machinery of the vessel as
far as was seen in the fore and aft
part is in good and efficient condition
with few defects of a minor nature
and the vessel is considered to be
worthy of service.*

*Examined by
Mr. J. H. [unclear]
on 20/5/27*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

