

Rpt. 9.

BOX CARD

No. 20964

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

22 APR 1930

HULL.

Date of writing Report	When handed in at Local Office	14.4.1930	Port of	HULL.
No. in Reg. Book.	Survey held at	HULL	Date, First Survey	Last Survey
26894	on the Machinery of the Wood, Iron or Steel	Sc "LIZZIE & ANNIE".	Apr. 2nd 1930	(No. of Visits one)
Tonnage { Gross 119	Vessel built at	N. Shields	By whom	J. Sofley & Sons. When 1877-6
Net 65	Engines made at	Newbury	By whom	Plenty & Sons Ltd When 1913
Nominal Horse Power { 27	Boilers, when made (Main)		(Donkey)	-
No. of Main Boilers	Owners	G. F. Birch & Sons (1919) Ltd	Owners' Address	(If not already recorded in Appendix to Register Book).
No. of Donkey Boilers	Managers		Port	Hull Voyage
Steam Pressure— in Main Boilers	If Surveyed Afloat or in Dry Dock	North Bridge AD.	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
in Donkey Boilers	(State name of Dock.)			

Last Report No. Port

Particulars of Examination and Repairs (if any) Condition.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

Do.

Donkey "

None.

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined? ho

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? ✓ If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.

Close fit.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done? Complete as to condition, but the L.M.C. is due and the Owners Representative stated that this will be carried out as soon as it can be conveniently arranged, in the near future.

how done.

The propeller, stern bush, sea connections and fastenings examined and found good.

General Observations, Opinion, and Recommendation:— The machinery of this vessel, (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B&H.S. 9,11, or *L.M.C. 9,11, 140 lb., F.D., &c.) as now seen, is in good condition and eligible in my opinion to remain as classed without fresh record of survey.

Survey Fee (per Section 28).

£ . . .

Fees applied for

10

Special Damage or Repair Fee (if any) (per Section 28.)

£ . . .

Received by me,

10

Travelling Expenses (if chargeable)

£ . . .

L. Moffatt.

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE. 13 MAY 1930

WED. 11 JUN 1930

Assigned

As now

© 2018



Lloyd's Register
Foundation

A.S. May due 4-30 - To hold no
surveys can be convenient of
owners.

Stockard

It is submitted that
this vessel is eligible to
remain as CLASSED.

③
2/3/20

John S. Stockard
Proprietary Co.
pt. ts.

N.B.-If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

60406

28 4/11

HULL

48835

as the roof →
"LIZZIE & ANNIE".
2-1981
21P1
W.M. omoh & judd f.
W.M. omoh & judd f.
W.M. (1981) omoh & judd f.

abull n
produced

P.I.
21
12

28 3M2 P.1.1 1A OF H
153(M)3M2 55.0-3M2 JUH 22
P.1.1 27 .22 - 10M JUH 22
E1 3K

SWELL

OF THIS SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

minnow at no depth
tall grass scattered overall the land out is 3.11
flounder at may be as deep as the dinner at the
swell near the in. flounder

the minnow are hard to collect all
top swell the dinner sparsely

comes out to minnow all

out to single land minnow loop is a nose way is
tall grass deep bottom dinner dinner sea around at minnow

