

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

MON. JUN 22 1896

Date of writing Report	17 June	1896	When handed in at Local Office	20/6/1896	Port of Hull			
No. in Reg. Book.	Survey held at	Boston	Date, First Survey	June 8 <sup>th</sup>	Last Survey			
421	on the Machinery of the Woods, Iron and Steel Company's "Lizzie & Annie"	Master	No. of Visits	2	Jane 16 <sup>th</sup> 1896			
Tonnage	Gross 99	Net 63	Vessel built at	St. Mields	By whom	Cotteray & Co.	When	1877. 6
Registered Horse Power	25	Engines made at	Newcastle	When	1877	Boilers, when made (Main) 1884 (Donkey) 1896		
No. of Main Boilers	One	Owners	Boston London J. J. Co.	Port	Boston	Voyage	London	
No. of Donkey Boilers	One	If Surveyed Afloat or in Dry Dock	Afloat Boston	(State name of Dock.)				
Steam Pressure in Main Boilers	55							
in Donkey Boilers	50							

Last Survey No. Port

## Particulars of Examination and Repairs (if any) Brice Loring

*Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.*

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

"

Donkey "

"

"

Yes

Now Now

If this was not done, state for what reasons?

-

And what parts of the Boilers could not be thus thoroughly examined?

-

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

-

Did the Surveyor examine the Safety Valves of the Main Boiler?

Yes

At what pressure were they afterwards adjusted under steam?

55 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Yes

To what pressure were they afterwards adjusted?

50 lbs

Has the propeller shaft been drawn and examined at this time?

-

If the Survey is not complete state what arrangements have been made for its completion?

-

The main Boiler opened out and examined internally and externally condition good. New Main Safety Valve spring loaded two valves 2" diam fitted other Boiler mountings overhauled. Examined under steam and the Safety Valve set to blow at 55 lbs per square inch.

New donkey Boiler fitted in place all Boiler mountings now new and new single 2" spring loaded safety valve fitted in place examined under steam and the safety valve set to blow at 50 lbs per square inch.

Insert character of ship and machinery precisely as in the Register Book.

CHARACTER	YEAR	MACHINERY AND BOILER SURVEYS (including date of N.I., if any).
<input checked="" type="checkbox"/> for Special Survey.		
Date of Last Survey and of Periodical Surveys		
	+ 90. 71 q. 94	B.S. 9. 95
S. S. Hub. No 3. b. 90		LMC 9. 94
S. S. Bos. No 1. q. 94		

General Observations, Opinion, and Recommendation:— *Ineligible in my opinion*

*(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0.95, B.C.M.S. 0.95 or M.L.M.C. 0.95, 140 lbs., F.D., &c.)*

To remain as classed and to be put in *B. S. 6.96* in the Register Book.

Fees or Registration Fee (per Sec. 27)	£ 1 : 0 : 0	Fees applied for	20/6/1896
Survey Fee (per Section 28) less 10% due	£ 1 : 0 : 0	Per	Rother.
Special Damage Fee (per Section 28)	£ 1 : 8 : 0	24	
Arranging Expenses (if chargeable)	£ 1 : 8 : 8	Received by me,	23/6/1896

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

State if Certificate is required.

Committee's Minute

TUES. JUN 23 1896

Signed

H. S. Loring  
H. S. Loring

Safety valves of main boiler also donkey  
boiler & it's mounting renewed

N.D.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that  
this vessel is eligible for  
THE RECORD P.S.L. 6. 96. 1. 23. 96.  
Working pressure of donkey boiler  
50 lbs. to be recorded in the  
Register Book

A.H.W.  
22.6.96

LR-FAF-SA13-188

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

No. in Su  
Reg. Book.

421 on t.

Master

Engines made

Boilers made

Registered Ho

Nom. Horse P

ENGINES,

Diameter of c

Diameter of T

Diameter of scr

No. of Feed p

No. of Bilge p

No. of Donkey

In Engine Ro

No. of bilge injec

Are all the bilge

Are all connecti

Are they fixed su

Are they each fit

What pipes are

Are all pipes, c

Are the bilge s

When were ster

Is it fitted with

BOILERS, S

No. and Descr

Date of test

each boiler

with easing gear

Length

Diameter of rive

Per centages of st

Size of compensat

Length of plain P

Working pressure

Pitch of stays to c

Material of stays

Material

Diameter at sma

Thickness M

Diameter of tubes

Pitch across w

thickness of girde

Working pressur

separately

holes Pitch

If stiffened with rin

Working pressure



© 2018

Lloyd's Register  
Foundation