

No. 3178

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report March 21st 1895 When handed in at Local Office in Port of Hamburg. (Received at London Office SAT 23 MAR 1895)

No. in Reg. Book 28 Survey held at Hamburg. Date, First Survey March 19th 1895 Last Survey March 20th 1895

on the Machinery of the Wood, Iron or Steel S. 3 Met. S. Bakun Master G. J. Meyer

Tonnage Gross 1664 Net 1093 Vessel built at H. Harlepool By whom H. Gray & Co. When 1886 YEAR. MONTH

Registered Horse Power 200 Engines made at H. Harlepool When 1886 Boilers, when made (Main) 1886 (Donkey) 1886

No. of Main Boilers 2 Owners Thosum Transport & Agency (Lim) Port London Voyage Batavia

No. of Donkey Boilers 1 Steam Pressure in Main Boilers 150 lbs If Surveyed Afloat or in Dry Dock in dry dock (State name of Dock.) Blohm & Voep dock

Last Survey No. _____ Port _____

Particulars of Examination and Repairs (if any) Surv. in dry dock

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Do. " Donkey " " " " "

If this was not done, state for what reasons? _____

And what parts of the Boilers could not be thus thoroughly examined? _____

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? _____

Did the Surveyor examine the Safety Valves of the Main Boiler? _____

At what pressure were they afterwards adjusted under steam? _____

Did the Surveyor examine the Safety Valves of Donkey Boiler? _____

To what pressure were they afterwards adjusted? _____

If the Survey is not complete state what arrangements have been made for its completion? _____

In dry dock I examined the fastenings of sea connections, propeller propeller shaft, which was drawn stern bush which was relined in lower part, and found all of these parts satisfactory.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.N. 3,01, B.&N.S. 3,01 or S.L.M.C. 3,01, 140 lb., F.D., &c.)

The machinery of this vessel being satisfactory, I beg to recommend that her Class be continued without new entry with regard to machinery.

Office or Registration Fee (per Sec. 27).....	£	10. 0	Fees applied for
Survey Fee (per Section 28).....	£	1. 1. 0	<u>21/3 1895</u>
Special Damage Fee (per Section 28).....	£	:	<u>L.L.M.C.</u>
Travelling Expenses (if chargeable).....	£	:	Received by me,
			<u>29/3 1895</u>

*State if Certificate is required No **FRI 31 MAY 1895**

Committee's Minute TUES. 26 MAR 1895

Assigned As now

M. Barentz
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.
Ch. Rick

*A On and of ten years
The steam launch was returned*

X.R.—If this Report is copied by Copying Press, especial care must be taken that the copying press is not so much cramped as to spread the ink, or cause it to show through to the other side.

*It is submitted that
this vessel is eligible to
remain AS CLASSED.*

*W.A.
23.3.95*

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2018

Lloyd's Register
Foundation