

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 23rd Sept 1896 When handed in at Local Office Cardiff (Received at London Office THUR. SEP 24 1896)

No. in Reg. Book 31 Survey held at Cardiff. Date, First Survey and Last Survey 22nd Sept 1896 (No. of Visits 1)

Tonnage Gross 1669 Net 1093 Vessel built at W. Hartlepool By whom W. Gray & Co When 1886 YEAR. MONTH. 6

Registered Horse Power 203 Engines made at 92 When 1886 Boilers, when made (Main) 1886 (Donkey) 1886

No. of Main Boilers 2 Owners Petroleum Transport & Storage Co Port London Voyage Callao

No. of Donkey Boilers 2 Steam Pressure in Main Boilers 150 lbs Surveyed Afloat or in Dry Dock East Bute Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. 33852 Port NWC Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

Do. " Donkey " " " " No.

If this was not done, state for what reasons? Said to have been done at Newcastle.

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓

At what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

To what pressure were they afterwards adjusted? ✓

Has the propeller shaft been drawn and examined at this time? ✓

If the Survey is not complete state what arrangements have been made for its completion? ✓

In compliance with letter received from the Newcastle Surveyors, visited this vessel to see blank flanges fitted for cutting off the ordinary pumping arrangement of two ballast tanks to be used for carrying liquid fuel; as however the vessel is going out to Callao burning ordinary fuel, these ballast tanks will be required until here arrival there; the flanges are on board, and the engineer states they will be fitted at Callao, where the oil installation will be put in use.

General Observations, Opinion, and Recommendation: This vessel's machinery

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,93, B.&M.S. 9,95 or Q.L.M.C. 9,93, 140 lb., F.D., &c.) appears eligible to remain as classed, without fresh record.

Office or Registration Fee (per Sec. 27)	£ 1	Fees applied for	18
Survey Fee (per Section 28)	£ 1		
Special Damage Fee (per Section 28)	£ 1	Received by me,	
Travelling Expenses (if chargeable)	£ 1		18

W. Liburn
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRI. SEP 25 1896

Assigned as now

S.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain IS CLASSIFIED.

[Signature]
24.9.96

[Faint, illegible handwritten text throughout the lined area]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

