

No. 14195.

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

WED. 7 AUG 1895

Date of writing Report	26.7.1895	When handed in at Local Office	6 AUG 1895	Port of	CARDIFF	
No. in Reg. Book.	Survey held at		Cardiff			
30	on the Machinery of the Wood, Iron or Steel S.S. Baker Standard		Date, First Survey	July 22 nd	Last Survey	July 24 th 1895
Tonnage	Gross 3708	Net 2375	Vessel built at	Newcastle	By whom	Armstrong Mitchell & Co. When 1893 - 2
Registered	293	Horse Power	Engines made at	When 1893	Boilers, when made (Main)	1893 (Donkey) 1893
No. of Main Boilers	2	Owners	(a Smart)	Port Manager	Voyage	
No. of Donkey Boilers	1	If Surveyed Afloat or in Dry Dock	Not least by Dr	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).		
Steam Pressure in Main Boilers	160	(State name of Dock.)				
in Donkey Boilers	100					

Last Survey No. Port

Particulars of Examination and Repairs (if any) Damage.

(Periodical Surveys, when held, must be reported in detail and narration in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Damage stated to have been caused by grounding when leaving Philadelphia on June 19th 1895 & also in River Garonne on July 7th 1895.

Propeller stuck in bush & with out started, shaft drawn examined & found in good order, bush reworked propeller refitted sea-cocks valves examined & over-hauled.

Note. The gear for burning liquid fuel has been (temporarily) disengaged and the tubes are now fired in the usual manner.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, I.M.C. 4.04 or $\frac{1}{2}$ I.M.C. 4.04, 140 lb. P.D., &c.)

as far as seen, is and in good order except in my opinion to remain as classed without fresh record of survey.

Office or Registration Fee (per Sec. 27)	£ - - - -	Fees applied for	10
Survey Fee (per Section 28)	£ - - - -		R.H.W.
Special Damage Fee (per Section 28)	£ 1.1.0		12/8/95
Travelling Expenses (if chargeable)	£ - - - -	Received by me,	

John Wallis
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute

Assigned

FRI. 9 AUG 1895
As now

© 2018

Lloyd's Register
Foundation