

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office) SAT MAR 6 1897

Date of writing Report 3rd Feb 1897 When handed in at Local Office 4th Feb 1897 Port of Newcastle

Survey held at North Shields Date, First Survey 24th Feb Last Survey 3rd March 1897
(No. of Visits 6)

on the Machinery of the Wood, Iron or Steel S.S. "Baku Standard" Master

Gross 3708 Net 2375 Vessel built at Newcastle By whom Armstrong Mitchell & Co When 1893-2
Engines made at 00 When 1893 Boilers, when made (Main) 1896 (Donkey) 1896
Owners A. Smart Port London Voyage

Number of Main Boilers 2.52. of Donkey Boilers 1
Working Pressure Main Boilers 160 Donkey Boilers 100
If Surveyed Afloat or in Dry Dock Mills & Barton Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned and expired.	Machinery and Boiler Surveys (Including date of N.B., if any).
+ 100 A 1 Spaz & R 1-97 Carrying petrol in bulk Burning liquid fuel - Spl		+ 2 M 6 2-93

Particulars of Examination and Repairs (if any) L.M.C.

Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and ideas being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? **Yes**

Do. " " Donkey " " " " **Yes**

Was it not done, state for what reasons? **-**

What parts of the Boilers could not be thus thoroughly examined? **-**

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? **-**

Did the Surveyor examine the Safety Valves of the Main Boiler? **Yes**

What pressure were they afterwards adjusted under steam? **165 lbs. 0"**

Did the Surveyor examine the Safety Valves of Donkey Boiler? **Yes**

What pressure were they afterwards adjusted? **80 lbs. sufficient for the requirements of vessel.**

Has the propeller shaft been drawn and examined at this time? **No. See previous report - 33563.**

Is the Survey not complete state what arrangements have been made for its completion? **Complete.**

The sea cohes & valves examined and found satisfactory except tail shaft
The cylinders, pistons, slides, all shafting in pumps & condenser and the machinery generally, examined and put in good order.

The main boilers and their safety valves examined & found satisfactory
The donkey boiler and its safety valves examined and found satisfactory
All safety valves tested under steam

10 tubes in main boilers renewed. Joints of main boilers drilled for thickness and found sufficient.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 95, B.&M.S. 9, 95 or L.M.C. 9, 95, 140 lb., F.D., &c.)
The Machinery is eligible in my opinion to remain as classed and to have fresh record. + L.M.C. 3-97

Office or Registration Fee (per Sec. 27)	£		Fees applied for	5. 3. 1897
Survey Fee (per Section 28)	£	5. 0. 0	Received by me,	
Special Damage Fee (per Section 28)	£	4. 10. 0		
Travelling Expenses (if chargeable)	£			

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUES MAR 9 1897 TUES MAR 16 1897 FRI, 10 SEP 1897 FRI, 12 NOV 1897

Assigned + L.M.C. 3, 97



10 tabs. removed in main binder

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this vessel is eligible for THE RECORD

L. M. C. 3. 77
The Surveyor should be requested to state what liquid fuel is still being used in the furnace of the boiler

[Handwritten signature]
6. 3. 97

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page]

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.