

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUES. 9 NOV 1897

Date of writing Report *5th Nov* 1897 When handed in at Local Office *8th Nov* 1897 Port of *Newcastle on Tyne*

No. in Reg. Book. Survey held at *North Shields* Date, First Survey *30th Oct.* Last Survey *2nd Nov* 1897 (No. of Visits *Three*)

29 on the Machinery of the ~~Wood, Iron or Steel~~ *S.S. "Baker Standard" Master*

Tonnage { Gross *3708* Net *2375* Vessel built at *Newcastle* By whom *Sir W. G. Arm. Mitchell & Co* When *1893* YEAR. MONTH. *2*

Registered Horse Power *293* Engines made at *do* When *1893* Boilers, when made (Main) *1893* (Donkey) *1893*

No. of Main Boilers *2* Owners *A. Stuart Esq.* Port *London* Voyage

No. of Donkey Boilers *1*

Steam Pressure— in Main Boilers *160* If Surveyed Afloat or in Dry Dock *in situ* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boilers *100*

Last Survey No. Port

Particulars of Examination and Repairs (if any) *Propeller + 100 A 1 Spat. dh 197*

CHARACTER for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned for new survey.	Machinery and Boiler Surveys (including date of N.S., if any).
<i>+ 100 A 1 Spat. dh 197</i>		<i>+ L.M.C 3.97</i>

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No*

Do. " Donkey " " " " *No*

If this was not done, state for what reasons? *Not done*

And what parts of the Boilers could not be thus thoroughly examined? *-*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *-*

Did the Surveyor examine the Safety Valves of the Main Boiler? *✓* At what pressure were they afterwards adjusted under steam? *L*

Did " " examine the Safety Valves of Donkey Boiler? *✓* To what pressure were they afterwards adjusted? *-*

Has the propeller shaft been drawn and examined at this time? *Yes* If spare propeller shaft fitted, state whether new? *-*

State the distance between lignum vite of stern bush and top of after bearing of screw shaft? *3/16"*

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? *complete*

Examined sea fastenings & found satisfactory
The tail shaft drawn in & examined & found satisfactory
A new propeller now fitted

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 91, B. & N.S. 9, 91 or L.M.C. 9, 93, 140 lb., E.D., &c.)

The machinery is eligible in my opinion to remain as classed without fresh record of Survey.

Office or Registration Fee (per Sec. 27)	Survey Fee (per Section 28)	Special Damage Fee (per Section 28)	Travelling Expenses (if chargeable)	Fees applied for
£	£	£	£	18
				Received by me,
				18

B. M. Dyer
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

FRI. 12 NOV 1897

Committee's Minute
 Assigned *As now*



Has a Survey also been held on Ship? If so, is the Report now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

Certificate to be sent to

Scut shaft examined, propeller removed.

V.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

*It is submitted that
this vessel is eligible to
remain as UNCLASSIFIED.*

1/19/97

LB-FAR-SA19-79

50

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]

MADE REPAIR
Reason
Date

ION OF THE

LET THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2018

Lloyd's Register
Foundation