

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

MIL 27 FEB 1903

Date of writing Report	When handed in at Local Office	26 FEB 1903	Port of Newcastle-on-Tyne
No. in Reg. Book.	Survey held at	Jarrow Stake	Date, First Survey
34	on the Machinery of the Wood, Iron or Steel	S.S. BAKU STANDARD	Last Survey
Tonnage { Gross 3708	Vessel built at	By whom S.W.G. Armstrong Mitchell, When 1893	(No. of Visits) 2
Net 2375	Engines made at	By whom Wallend Shipway Co., When 1893	YEAR. MONTH.
Registered Horse Power 293	Boilers, when made (Main)	1893 - 2 (Donkey)	
No. of Main Boilers 2	Owners European Petroleum Ltd Port London	Voyage Laid up	
No. of Donkey Boilers 1	If Surveyed Afloat or in Dry Dock	Jarrow Stake	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Steam Pressure— in Main Boilers 160 in Donkey Boilers 90	(State name of Dock.)		CHARACTER Date of Special Survey. Date of last Survey and of Periodical Surveys.
Last Survey No. 4384 Port Nwe			Years Abridged since last Survey.
Machinery and Boiler Survey (including date of N.B., if any).			

E.I.O.O.F.I. 1894/95	F.I.M.C.
6.07	M.I. 7.02
S.S. Nwe N° 22-02	B.S. 9.07

Has a Survey also been held on Ship? If so, is the Report sent now, or when will it be sent?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

Do. " Donkey " "

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Has the propeller shaft been drawn and examined at this time? ✓ If spare propeller shaft fitted, state whether new? ✓

State the distance between lignum vite of stern bush and top of after bearing of screw shaft? ✓

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? ✓

Complete

Adjusted Donkey Boiler Safety Valves to 90 lbs

707 Particulars of Boiler Survey in Newcastle Report N° 43821

General Observations, Opinion, and Recommendation:—The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, before, working pressures, &c.; thus, for example, B.S. 0.00, B&M.S. 0.00 or S.L.M.C. 0.00, 140 lb., N.D., &c.)

in my opinion is eligible to remain as classed & to have a void of

F.I.M.C. 7.02

The Surveyors are requested not to write on or hold the space for Committee's Minute.

Office or Registration Fee (per Sec. 27)	£	1	1	Fees applied for
Survey Fee (per Section 28)	£	1	1	10
Special Damage Fee (per Section 29)	£	1	1	
Travelling Expenses (if chargeable)	£	1	1	Received by me, 10

* State if Certificate is required.

Committee's Minute

TUES. 3 MAR 1903

Assigned

L.M. 6.7.03

G. R. Dryden Toynes
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2018

Lloyd's Register
Foundation

