

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

SAT. 24 SEP 1904

Date of writing Report 8th Sept 1904 When handed in at Local Office

No. in Reg. Book Survey held at Port Talbot.

34 on the Machinery of the Wood, Iron or Steel S.S. "Baku Standard" Master
 Tonnage Gross 3708. Vessel built at Newcastle By whom Sir W. G. Armstrong Mitchell & Co. When 1893-2
 Net 2375. Engines made at to By whom Wallsend Slip. C. (Linn) When 1893.
 Registered 293. Boilers, when made (Main) 1893. (Donkey) 1893.
 Horse Power 293. No. of Main Boilers 2 Owners European Petroleum Co. Ltd Port London Voyage
 No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock Port Talbot Bearing TS YB. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 Steam Pressure in Main Boilers 160
 in Donkey Boilers 90

Last Survey No. Port

Particulars of Examination and Repairs (if any) B.S. & Dooling.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. Donkey " " " Yes

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? Not Adjusted.

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam? Not Adjusted.

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boiler? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? " " " , and of the Donkey Boiler? "

Did the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boiler? Yes

Has the propeller shaft been drawn and examined at this time? Yes If spare propeller shaft fitted, state whether new? "

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? 1/8.

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? On Vessel's Return in a few months.

Vessel placed in dry dock, fastenings of sea cocks examined.

Tail shaft drawn in and examined, shaft replaced and spare propeller fitted and secured.

Main and donkey boilers opened and examined throughout, their safety valves taken adrift and examined.

To complete B.S.

All safety valves to be adjusted under steam.

General Observations, Opinion, and Recommendation:— The machinery of this vessel so far

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9-04, B.C. 9-00, or S.E. 9-00, 140 lb., F.D., &c.)

as seen is in an efficient condition eligible in my opinion to remain as classed with fresh record for tail shaft of 9-04 and B.S. 9-04 when the survey has been completed.

Office or Registration Fee (per Sec. 22)

Survey Fee (per Section 22)

Special Damage or Repair Fee (if any) (per Section 22)

Travelling Expenses (if chargeable)

*State if Certificate is required

		Fees applied for
		23 rd Sept 1904
£ 2 - 0 - 0	4 0	
		29-9-04 John Pollock
£ 16 9		
£ 4 . 6		Received by me
£ 2 - 0 - 6	28 . 9 . 04	

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUES. 27 SEP 1904

Assigned note as now

WED. 28 DEC 1904

Deferred

TUES. 31 JAN 1905

©2018



Lloyd's Register Foundation

B.S. due 10.00 to complete on
Photo in a few
months.

Sever Shipp Examined

It is submitted that this
vessel WILL BE eligible for
the reward. B.S. I. or where
all safety rules have been
observed under rule.

K. Bell.

S. 9.00 24.9.00

N.B. - If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

© THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

