

92 S.S. #02 due 5-14 now held

It is submitted that

THE RECORD + X. PHIL. 7-217

I.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

No. 70107

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

THU - AUG 1917

Survey held at	Jarrow	Date, First Survey	8 - AUG 1917	Port of Newcastle on Tyne
on the Machinery of the Wood, Iron or Steel	5/6 "BAKU STANDARD"	Last Survey	21st July 1917	No. of Visits
Gross 3708	Master A. Torrance	YEAR	MONTH	
Net 2375	Vessel built at Newcastle	By whom Sir W. Armstrong, Middlesbrough 1893	2	
d 293	Engines made at Newcastle	By whom Wallsend Slipway Co. When 1893		
n Boilers 20B	Boilers, when made (Main) 1893	(Donkey) 1907		
rey Boilers 1	Owners J. J. Jacobs & Co Ltd	Port Swansea Voyage		
ssure - Boilers 1604	If Surveyed in Dry Dock	Particulars of Classification (which must be inserted precisely as in Register Books & Supplements).		
ay Boilers 1044	(State name of Dock) Jarrow			

report No. Port

Particulars of Examination and Repairs (if any) LMC.

Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarized at the end of the report. State also the initiation of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not accepted?

Was a damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

CHARACTER.	Boiler Survey Date of last Survey and at Portsmouth Survey	Boiler Survey (including date of R.B., if any).
+ - 100A	Guardale 7-13	+ LMC 7-14
SSShL N 2 - 5 - 06	MS 7-16	
SSShL N 7 - 11	T 3 7-16	
Carrying Petroleum in bulk NO 804		

Yes

Yes

not done, state for what reasons?

parts of the Boilers could not be thus thoroughly examined?

special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler?

Yes

To what pressure were they afterwards adjusted under steam?

165%

Surveyor examine the Safety Valves of Donkey Boiler?

Yes

To what pressure were they afterwards adjusted under steam?

95%

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes, and of the Donkey Boiler?

Yes

Surveyor examine the drain plugs of the Main Boilers?

Yes

, and of the Donkey Boiler?

Yes

Surveyor examine all the mountings of the Main Boilers?

Yes

, and of the Donkey Boiler?

Yes

Screw shaft now been drawn and examined?

No

Is it fitted with continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

Shaft now been changed? ✓ If so, state reasons?

✓

Screw shaft now fitted new?

✓

Has it a continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

Distance between lignum vitae of stern bush and top of after bearing of screw shaft?

Clearance 1/8"

Survey is not complete state what arrangements have been made for its completion and what remains to be done?

mined the main & Donkey boilers with their mountings & found condition good.

mined the cylinders, pistons & slide valves, condenser, air, circulating, feed & auxiliary, & cargo pumps. Crank shaft, thrust shaft, Propeller, & fastenings of sea cocks & valves.

Cargo now done. LP slide valve chest cover renewed. all check valves renewed. C C screwed stays renewed (2) two dogs for manhole door. other minor items effected. Main funnel renewed.

ing to waste on Boiler room tank top, the tank has been cut off, by blank if on the inlet valve from sea & suction valve made none return type. Safety valves adjusted as above noted

General Observations, Opinion, and Recommendation: - The machinery of this vessel so

clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Books, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c. Thus, for example, R.S. 9-11, R.M.C. 9-11, or + L.M.C. 9-11, 140 lb., F.D., &c.)

as seen is in good condition and in our opinion eligible to remain classed & have notation of + L.M.C. 7-14 in the Register Books

Fee (per Section 28)

£ 5.00

Fees applied for

8 - AUG 1917

Damage or Repair Fee (if any)

(per Section 28)

Expenses (if chargeable)

Received by me,

11/8/17

15/8/17

Committee's Minute

FRI 17 AUG 1917

red

L. H. J. Y. J.

FRI 18 JAN 1918

MACHINERY CERTIFICATE

WRITTEN, 27.8.17

Thomas M. Brooks & Co, Murchison

Engineer Surveyor to Lloyd's Register of Shipping.

Yield

Insert Character of ship and Machinery proceeding on the above Register Books.

If a Certificate required? If so, to be sent to _____