

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report April 5 1899 When handed in at Local Office		(Received at London Office THURS. 6 APR 1899)	
No. in Reg. Book Survey held at Leith		April 5 1899 Port of Leith	
1096 on the Machinery of the Wood, Iron or Steel ½ Stettin		Date, First Survey March 28 Last Survey April 1 st 1899	
Tonnage	Gross 889	Master L. Robertson	(No. of Visits 2)
Net	538	YEAR MONTH	
Registered	98	By whom Barclay Curle & Co	When 1864 11
Horse Power	1	Engines made at Leith	When 1889
No. of Main Boilers	1	Boilers, when made (Main) 1889 (Donkey) 1889	
No. of Donkey Boilers	1	Owners J. Currie & Co (Managers) Port Leith	Voyage Baltic
Steam Pressure— in Main Boilers	150	If Surveyed Afloat or in Dry Dock Alexandria dry dk	
in Donkey Boilers	50	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
(State name of Dock.)			

Last Survey No. Port

Particulars of Examination and Repairs (if any) BS 1899.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? **yes**

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

yes

To what pressure were they afterwards adjusted under steam?

150 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

yes

To what pressure were they afterwards adjusted under steam?

50 lbs.

Has the propeller shaft been drawn and examined at this time?

yes

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? **8**If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? **complete.**

bocking. Vessel placed on blocks in dry dock. Propeller, propeller shaft and fastenings of sea connections examined.

B.S. The (1) main and (1) donkey boiler examined internally and externally and safety valves of same examined and adjusted as above.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.97, B.A.M.S. 9.97 or S.L.M.C. 9.97, 140 lbs., F.D., &c.)

now as far as seen in good and safe working condition and is eligible in my opinion to remain as classed and to have the record B.S. 4.99.

Office or Registration Fee (per Sec. 27) £ 1.10.0
Survey Fee per Section 28 £ 1.10.0
Special Damage Fee (per Section 28) £ 1.10.0
Travelling Expenses (if chargeable) £ 1.10.0

Fees applied for
Apr 5 1899
Received by me,
21.4.1899

Harry Clarke
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute

FRI, 7 APR 1899

Assigned

W. A. G.

Scanned on
Main + Tanker (Bairns examined)

NE—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

A.C.H.
It is submitted that
this vessel is eligible for
THE RECORD. B.S. 4. 99.

6. 4. 99

© THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.