

~~REPORT of SURVEY for REPAIRS, &c.~~

Date of writing Report 25-8-1925 When handed in at Leith after 26-8-1925 Port of Leith  
No. in Reg. Book Survey held at Leith Date, First Survey 19-8-1925 Last Survey 22-8-1925  
33996 on the Wood, Iron or Steel Sc. 2 Mot St. "STETTIN"

## TONNAGE:-

GROSS 846

UNDER DECK 857

NET 528

Built at Glasgow By whom Barclay, Gourock 1860 When 1864 - 11  
Owners Leith, Hull, Hamburg. S.P. Co. Owners' Address  
Managers J. Currie & Co Port belonging to Leith

Surveyed Afloat or in Dry Dock? Both Name of Dock Victoria P. of W. D. Destined Voyage Hamburg via London

WB=Cell DB or DBa feet; ue&b feet; f feet  
total capacity tons. FPT tons; APT tons; MT tons

All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 16611 Port LTH

## Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER  
① Special Survey  
② of Admiralty and of  
Portugal Survey  
③ Maritime and River  
Survey  
(including date of M.R.S. if any).

‡ A. I L.M.C. 11.244

11.244 + N.B. 11.244

S.S. LTH 5TH NO 3-11.244

NDB 24

T.S. 11.244

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Yes, not required Society's Freeboard (if assigned) as painted on Ship and now verified 2 n. 52 in.

Was a damage report made by anyone else? If so, by whom? D. A. Connell & Son

## REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage.

Alleged to have been caused by colliding with the s.s. "City of Athens" off Blankenese on 14<sup>th</sup> August 1925 whilst on a voyage from Hamburg to London. Found. Ficastle deck, port side indented.

Now done Vessel placed in dry dock the bottom & rudder, cleaned, examined & coated. Freeboard verified: No 2 shell plate (foc'sle deck spec) renewed: 3 frames in way of came part renewed: 4 ditto faired in place: Nos 2 & 3 deck strakes plates renewed: No 4 ditto faired in place; Strakes bar & coppered & part renewed: 4 deck beams part renewed: 8 pitch pine deck planks renewed & caulked & payed. All repairs examined on completion & found satisfactory. Steel work coated as necessary.

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	2. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed	1	5			4	2		
Removed and Paired or Repaired	-	4	V	1			1	
Paired or Repaired in place	-	4						

## PRESENT CONDITION OF THE

Decks	good	State if Tanks have been examined inside		Diking, Plates under Sounding Pipes		Copper, or T.M. of Wood Vessels	
Caulking of Decks	good	State if Tanks now tested		Engine Room Skylights	good	(State if on Paint.)	
Coamings	"	Bulkheads	over forecastle	Oil & Gasoline Openings, Lids, &c.	"	When put on, Month	Year
Beams & Fastenings	"	Ceiling	"	Scuppers	"	Boats	good
Outside Plating	"	Cement or Asphalt	(State which.)	Cargo Hatchways	"	Masts, Ropes, &c.	"
Breasthooks	"	Rudder	good	Hatches	"	Condition, how ascertained	from deck
Transoms	"	Steering gear and its connections	"	Planking of Wood Vessels		(State if wedges removed)	no
Frames	good	Windlass	"	Caulking	dito	Anchors, No. of	70 15 1.K.
Reverse Frames	"	Have Pumps now been examined and found efficient?	"	Treenails	dito	Cables (State if new ranged)	no
Longitudinals	"	Have Shut-off Valves now been examined and found efficient?	"	Breasthooks & Stemson	dito	" length	
Transverses	"	Have Watertight Doors now been examined and found efficient?	"	Transoms, Pointers, & Crutches	dito	(on board)	
Floors	"	Have Ventilators and their Coamings been examined and found efficient?	yes	Timbers of Frame at openings	dito	" Rule length	
Knees	"			Ditto ditto other places	dito	size	
Stringers	"			Stringers, Clamps & Shells	dito	Hawsers & Warps	good
Inner Bottom Plating	"			Salting	dito	Standing & Running Rigging	"

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.25," or "to remain as classed and to have record of survey, 1.24, and the notations of No. 1-24 and PND15, &c."

This vessel is now in good & efficient condition & eligible to remain unclassed with fresh record of survey 8.25.

Survey Fee (per Section 89) £ 1 1 1

Special Damage or Repair Fee (if any) £ 3 1 3 1 -

Travelling Expenses (if chargeable) £ 1 1 1

Second Surveyor's Fee (if any) £ 1 1 1

Fees applied for,  
26-8-1925.

Received by me,

31-8-1925

666

R. J. Easthope.  
Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUES. 1 SEP 1925

Character Assigned B

© 2018



Lloyd's Register  
Foundation