

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

27 AUG 1925

Date of writing Report	25 - 8 - 1925	When handed in at Local Office	26 - 8 - 1925	Port of Leith
No. in Reg. Book.	Survey held at	Leith	Date, First Survey	19 - 8 - 25
33986	on the Machinery of the Wood, Iron or Steel Ac. 3 Mst At "STETTIN"		Last Survey	20 - 8 - 1925
Tonnage	Gross 876 Net 528	Vessel built at Glasgow Engines made at Leith	By whom Barclay, Curle & Co. When 1864 - 11	(No. of Visits 400)
Horse Power	98	Boilers, when made (Main) + N.B. H. 24 Owners Leith, Raff. & Hamburg, S.P. Co Ltd	By whom Hawthorn, & Co. When 1889 (TRIPLED) (Donkey) N.D.B. 24	
No. of Main Boilers	15. 8.	Managers J. Barrie & Co	Port Leith Voyage Hamburg to London	
No. of Donkey Boilers	1	If Surveyed Afloat or in Dry Dock P. of 10 ale. (Dry)	(If not already recorded in Register Book)	
Steam Pressure - in Main Boilers	150 lbs	(State name of Dock)	Particulars of Classification (which must be inserted previously as in Register Book & Supplements).	
in Donkey Boilers	80 "		CHARACTERS + for Special Survey, Date of last Survey and of Periodical Surveys	

Last Report No. Port

Particulars of Examination and Repairs (if any) Damage

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined Yes, not required

Was a damage report made by anyone else? If so, by whom? D. A. Cornwell & Son

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. Donkey

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? 2 liners Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated?

Has shaft now been changed? No If so, state reasons.

Is the shaft now fitted new? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated?

State the distance between lignum vitum or bearing metal of stern bush and top of after bearing of screw shaft? 32

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done? Complete

Damage alleged to have been caused by colliding with the ship "City of Alton" off Blankenese on 14th Aug 1925 whilst on a voyage from Hamburg to London

Found. Approximately 18" broken off the propeller blades (4 off).
Now done! Tail shaft drawn, examined & found in order. The spare propellers have now been fitted & found satisfactory. The broken propeller has been placed ashore where new ends will be burnt on. On completion the propellers will be placed aboard as spare.
Sea-coal connections & stern bush examined & found in order.

General Observations, Opinion, and Recommendation:— The machinery of this vessel
(State clearly what alterations, if any, are suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.1, B.M.C. 9.11, or C.L.M.C. 9.11, 149 lbs. F.D., &c.)
 is now in a safe working conditioneligible to remain as classed.
 with notation for T.S. 8. 25

Survey Fee (per Section 28).....

Fee applied for
26-8-1925

Special Damage Repair Fee (if any)
(per Section 28.)

2. 2 -

Received by me,

TRAVELLING EXPENSES (if chargeable)

31-8-1925

Committee's Minute

TUES. 1 SEP 1925

Assigned

As now

R. J. Castloope.

Engineer Surveyor to Lloyd's Register of Shipping.

© 2018



Lloyd's Register
Foundation

Damage through collision
between hull & container ship/bulk carrier

N.B.-If this Report is copied by copying firms, special care must be taken that the copying paper is not too much dampened so as to spread the ink, or to cause it to show through to the other side.

It is understood that
this Report is given up to
Commission as CLASSIFIED.

S.P.25

L.R.
29/9/2015