

No. 29197

Report of Survey for Repairs, &c., of Engines and Boilers.

THURS. 1 FEB 1894

Date of writing Report.	When handed in at Local Office	Jan. 30 th 1894	Port of	Newcastle
No. in Book.	Survey held at	S. Shields & Wallend	Date, First Survey Jan.	8 th
628	on the Machinery of the	Wood, Iron	Last Survey Jan.	30 th 1894
Gross tonnage	Vessel built at	Sunderland	(No. of Visits)	2
Net	Engines made at	Greenock	Master	
Registered Horse Power	Owners	A. Guart	YEAR	1866 - 11
No. of Main Boilers	If Surveyed Afloat or in Dry Dock	Smiths Pontoon River	MONTH	
Steam Pressure in Main Boilers	(State name of Dock.)	Voyage		
in Donkey Boiler				

Last Survey No. 230 Port

Particulars of Examination and Repairs (if any) Docking

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey "

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys.	Years Ago	Machinery and Boiler Surveys (including date of S.R., if any).
✓	90A1	I.M.C 12, 92
	12, 92	✓ S.S. Newc. No 3-86
		✓ S.S. Newc. No 1-90

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

no opportunity afforded.

Valve laying up.

Propeller & sea cock fastenings in good condition

Owners have been advised that boiler survey is now overdue, but as vessel is laying up state that notice will be given before the vessel leaves.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 0,02, B.M.S. 0,02 or T.L.M.C. 0,02, as the case may be.)

The machinery of this vessel as far as seen, is now in good & safe working condition eligible in my opinion to remain as classed without fresh record of Survey.

Office of Registration Fee (per Sec. 27) £ 1 1

Survey Fee (per Section 28) £ 1 ✓ 1

Special Damage Fee (per Section 28) £ 1 1

Travelling Expenses (if chargeable) £ 1 1

Fees applied for

Received by me,

18

TUES. 19 JUL 1894

18

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute FRI 2 FEB 1894

Assigned Deferred

It is submitted to
this vessel is eligible
remain AS CLASS 2.

Subject to the
Coast Survey being held
before the General Board:

seen 12/13
1-2-94

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

NOT THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.