

REPORT of SURVEY for REPAIRS.

20541

No. in Reg. Book. **No.** 13 Survey held at London Date Oct 6th 1868
 on the Ship "Thermopylae" Master Robert Campbell
 Tonnage 947 built at Aberdeen When built 1868, 8 mo
 By whom built Good Owners Thompson & Co.
 Port belonging to Aberdeen Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Janal (Dry Dock & East India) OK

Last Survey, No. 2424 Port Aberdeen Classed 17 A. 1.
 REPAIRS 9, 60

Now done,

The seams spungarred and the Bottom sheathed with Yellow Metal—
 Three painting beams of 8" bulb iron, with double angle irons on their top edges, fitted forward and a wooden cross piece under the Bowprit in the Forecastle, secured with a pair of wood lodging knees—

Present Condition of the

Decks <u>good</u>	Tonnage <u>YM</u> Bolls	Windlass and Copstan
Waterways <u>✓</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>good</u>
Comings <u>✓</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>✓</u>	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>and</u>
Planksheers <u>✓</u>	Keelsons	Sails
Sheerstrakes <u>✓</u>	Clamps and Shelves	Anchors No. of <u>3 B 1 S 2 M</u>
Topsides <u>✓</u>	Ceiling <u>new</u>	Cables <u>efficient</u>
Wales <u>✓</u>	Rudder	Hawsers and Warps
Plank (Bottom) and Counter <u>✓</u>	Copper <u>YM</u> When put on <u>new</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>	

She is in good condition, fit in our opinion to remain as classed 17 A. 1.

The Amount of Fee.....£ : : is received by me,
 Special..... : :
 Certificate (if required) : :

Committee's Minute 20th October 18 68

Character assigned 17 A. 1

Robert Campbell



© 2018

Lloyd's Register Foundation