

"CUTTY SARK"

March 1<sup>st</sup> 1951. At the request of Mr Rawlinson (Chief Engineer) & with the approval of Mr Lethbridge superficially examined the above vessel in Westwall Dry Dock.

In attendance Mr C.R. Waddox (Shipyard engineer Retired)  
Mr \_\_\_\_\_ (Masterwright foreman )  
Mr Briggs Mr Robbs - Mr Thomas (on Mr Rawlinson's staff).

Mr Waddox stated that from internal sights rigged prior to dry docking no longitudinal movement was observed during dry docking. His process of docking, + that on re-sighting about 12 hours after the dock had been pumped dry a trackage of only 5½" was recorded from his sights.

It was observed that the sheathing while generally intact was torn & perforated in places & had become generally brittle & (light hammer tapping causing local perforation). "Brittleness" apart from evanescent down down during dry docking the vessel had not been in any way prepared for survey & the following recommendations were made:-

Bottom sheathing to be removed as regards exposing bottom planking in indicated places forward amidships & aft. In the vicinity of garboards, wood keel & plank ends (below sternpost) & in way of apparent damage to face of stem. Timber exposed by removal of sheathing to be scraped bright collar at both of woodwork marks to be removed

6 frames - plank bottom fastenings each side to be drawn ~~carefully to be tested~~. Mr Rawlinson who attended later re-enacted Mr Waddox's procedure with these recommendations & I was informed that the vessel would be ready for further examination on the morning of Wed. March 7<sup>th</sup>.

It was observed that the vessel appeared to be sitting firmly on suitable soft wood slabs on top of keel blocks & that bilge shores had been fitted port & starboard.

It was stated that these bilge shores had been fitted when the dock had been pumped & after the vessel had settled on her blocks.

It is known that the ship is deficient in the matter of keel bolts bolt fastenings & that her floor plates fastenings have become seriously wasted.

It was observed that the metal sheathing on the sides of the wood keel was somewhat rotted throughout the length of the keel & it is considered that this condition might suggest minor vertical movement between wood keel & garboards.

No arrangements have been made for respect  
of shifting or moving vessel.

It was suggested to Mr Rawlinson that a survey be made on March 7<sup>th</sup> the Cutty Sark be taken to dry dock at Westwall dock with a view to this arrangement.

Committee report in preference to the expression of  
isolated opinion & it is understood that this writing  
may be arranged.

H.R.



© 2018

Lloyd's Register  
Foundation

LR-FAF-SAB-42