

573

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUES 5 NOV 1893

o. 513. Date of Writing Report		29 Sept. 1893	Port of Shanghai	Date, first Survey	24 Sept. 1893	Last Survey	25 Sept. 1893	Master	Cormack	No. of Visits	2	
o. in Book	Survey held at Shanghai	on the Machinery of the S.S. Strathleven	Gross 2436	Nage	Net 1588	Vessel built at Port Glasgow By whom Blackwood & Gordon When 1875 No. 66	gistered	220	Engines made at Glasgow When 1875-89 Boilers, when made (Main) 1889 (Donkey) ?	of Main Boilers	2	Owners Burrell & Son Port Glasgow Voyage New York
of Pressure	Main Boilers	160	If Surveyed Afloat or in Dry Dock	New Dock	(State name of Dock.)	Donkey Boiler	56					

Class of Vessel & Machinery ~~Ex 100 A 1 9.92~~
 (As in Register Book, including dates of S.S. Gte. N. 3-109
 Special Surveys of Ship and
 of last Boiler Survey.) LMC 10/93 & NB 10/93

st Survey No. 3 Port Glasgow

Particulars of Examination and Repairs (if any)

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from

causes due to other causes. State also the dates and initials of any letters respecting this case

be Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Boilers not surveyed

Do. " Donkey " "

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

he Surveyor examine the Safety Valves of the Main Boiler? **No**

at pressure were they afterwards adjusted under steam?

he Surveyor examine the Safety Valves of Donkey Boiler? **No**

at pressure were they afterwards adjusted?

Vessel in dry dock undergoing portion of special survey No. 1.
 Propeller, stern bush and fastenings of sea connections examined
 not found in good condition.

Item shaft drawn out found in good condition.

Now done:-

Lignum vita in stern bush renewed.
 Seacock examined & ground.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification and notation of the vessel's machinery in the Register Book, consequent upon this survey; thus, for example, B.S. 1.91, B.C.M.S. 1.91, or T.L.M.C. 1.91, as the case may be.)

Recommend the vessel's machinery remain as classed without fresh record of survey.

For Registration Fee (per Sec. 27) £ 2 - - -
 by Fee (per Section 28) 52 4 - - -
 al Damage Fee (per Section 28) £ - - - - -
 elling Expenses (if chargeable) £ - - - - -

Fees applied for
 2/9 1893
 Received by me,
 2/9 1893

H. J. Romm
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

TUES. 26 MAR 1893

Committee's Minute

TUES. 7 NOV 1893

TUES. 23 OCT 1894

Assigned

as now.

LR-FAF-SAH-86

LR-FAF-SAH-23

© 2018



Lloyd's Register
Foundation