

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey (No. of Visits)

86571 on the Wood, Iron or Steel To motorship Yasukuni Maru

TONNAGE:- Built at Kagasaki By whom Mitsubishi Josen Kaisha, Ltd. When 1930 9

GROSS 11933 Owners Hippen Jusen K.K. Owners' Address

UNDER DK. 8373 Managers Port belonging to Tokyo

NET 7147

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell DB or DBa feet; uE&B feet; f feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.

Last Report, No. M620 Port Keb

CHARACTER. (For Special Survey, Date of last Survey and of Periodical Surveys.)	Machinery and Boiler Surveys (Including Date of S.M., if any).
+ 100 M	+ LMC cl 2.39
with freeboard	2.39
12.39	DBS 12.39
	AP 8.37
16 yka to 2.39	S 2.39
	THOYD'S RMC 5.40
	oil log

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year.
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length (on board) mean diam.
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without 'fresh record of Survey,'" "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£		Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£		19
Travelling Expenses (if chargeable)	£		Received by me,
Second Surveyor's Fee (if any)	£		19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE. 28 JAN 1941

Character Assigned

8 Unit class on W's
White Open reprint of Ref. BK.
" Koh

23 JAN 1941

