

No. 53785

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

WED. 28 OCT 1892

Date of writing Report	Oct 25 1892	When handed in at Local Office	Port of London.
No. in Reg. Book.	Survey held at London.		Date, First Survey Oct 14 1892
286	on the Machinery of the Wood, Iron or Steel S.S. "GLENFRUIN"		Last Survey Oct 17 1892 (No. of Visits)
Tonnage	Gross 2981	Net 1892.	Master T. Norman.
Registered Horse Power	330	Vessel built at Glasgow.	YEAR. MONTH.
No. of Main Boilers	Two	Engines made at Newcastle When 1891	Boilers, when made (Main) 1891 (Donkey) 1891
Steam Pressure— in Main Boilers	160 lbs	Owners M. Greger Gow & Co.	Port Glasgow. Voyage China.
in Donkey Boiler	—	If Surveyed Afloat or in Dry Dock London Graving D.	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port

Particulars of Examination and Repairs (if any) Condition.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Whilst the vessel was in dry dock, examined propeller, stern bush & sea connections fastenings, all found to be in good condition.

CHARACTER. X for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned now in use.	Machinery and Boiler Survey (including date of N.B., if any).
X 100 A-1 3.92. SS. Lon No. 2.89		X L.M.C. 10.91.
		X N.B. 10.91

Insert character of Ship and Machinery precisely as in the Register Book.

General Observations, Opinion, and Recommendation:— This vessel's machinery is now in good condition & in my opinion the vessel is eligible to remain as classed in the Register Book.

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 0.02, B.&M.S. 0.02 or X.L.M.C. 0.02, as the case may be.)

Office or Registration Fee (per Sec. 27)	£	1	1	Fees applied for
Survey Fee (per Section 28)	£	1	1	18
Special Damage Fee (per Section 28)	£	1	1	
Travelling Expenses (if chargeable)	£	1	1	18

* State if Certificate is required

Committee's Minute

FRI 28 OCT 1892

Assigned

as now.

Engineering Surveyor to Lloyd's Register of British and Foreign Shipping.

Mr. Salmon.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

C.W.
26.10.92