

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office) WED. 2 NOV 1898

Date of writing Report	1 Nov 1898	When handed in at Local Office
No. in Reg. Book.	Survey held at <u>London</u>	IN Port of <u>London</u>
382	on the Machinery of the <u>Wood, Iron or Steel</u>	Date, First Survey <u>31 Oct</u>
Tonnage	Gross <u>366</u>	Last Survey <u>31 Oct</u>
Net	<u>176</u>	1898
Registered Horse Power	<u>60</u>	No. of Visits
No. of Main Boilers	one	Muster <u>Kerr</u>
No. of Donkey Boilers	one	YEAR. MONTH.
Steam Pressure		
In Main Boilers	<u>160 lbs</u>	When <u>1890</u> - 1
In Donkey Boilers	<u>80 lbs</u>	When <u>1890</u> (Donkey) <u>1890</u>
Vessel built at <u>London</u>	By whom <u>R Thomson</u>	
Engines made at <u>Dundee</u>	When <u>1890</u> Boilers, when made (Main) <u>1890</u>	
Owners <u>A. F. Blackader</u>	Port <u>London</u> Voyage <u>Croating</u>	
¶ Surveyed Afloat on <u>Dry Dock</u> Regent Canal <u>DK</u>	(State name of Dock)	

Last Survey No. 8886 Port LthParticulars of Examination and Repairs (if any) Part L.M.L.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " "

If this was not done, state for what reasons? No

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? NoDid the Surveyor examine the Safety Valves of Donkey Boiler? NoHas the propeller shaft been drawn and examined at this time? No

State the distance between lignum vite of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Examined Main & Donkey Boilers under steam & adjusted safety valves to working pressures.

Attention was drawn to what remains to complete L.M.L. but nothing opened for exam.
To complete Special Survey - All piston & cylinder, IP slide valve and all shafting to be opened for examination.

General Observations, Opinion, and Recommendation:—The Machinery of this vessel,

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.97, B.M.S. 9.97 or Q.L.M.C. 9.97, 140 lb. F.D., &c.)

As far as seen, is now in a safe working condition & eligible, in my opinion, to have B.S. 10.98 Recorded in the Register Book, and + L.M.L. 10.98 when the same has been completed as above. (See Letter Report No 8886).

Office or Registration Fee (per Sec. 27)	£	Fees applied for
Survey Fee (per Section 28)	£	<u>.18</u>
Special Damage Fee (per Section 28)	£	
Traveling Expenses (if chargeable)	£	

© State if Certificate is required

Committee's Minute

Assigned

FRI. 4 NOV 1898

FRI. 4 NOV 1898

FRI. 10 MAR 1899

TUES. 21 NOV 1899

FRI. 29 DEC 1899

Thomas Blackader
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

© Certificate to be sent to

S.S. N: 2: Party has completed
their service.

It is submitted that
this vessel is eligible for
THE RECORD. B. S. 10.98.
and ~~is~~ L.M.C. 10.98 when
H.P. Gilders and piston
are lined and all
internal shafing
has been examined

A.C.H.

2.11.98

S.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.