

THUR. 28 DEC 1899

No. 61757.

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report: Dec 27<sup>th</sup> 1899 When handed in at Local Office

Port of

London

20/12 18 99

No. in Reg. Book. Survey held at London Date, First Survey 19/12/92 Last Survey 20/12/99  
6103 on the Wood Iron & Steel S.S. "Robin" No. of Vessel Master WessTONNAGE: 366 Built at London By whom A Thomson When 1890 - MONTH  
GROSS 366 Owners Robin S.S.C. Ltd (A. F. Blackader) Port belonging to London.  
UNDER D.K. 273  
NET 176

Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; ue&amp;B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 17470 Port Gb

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &amp;c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this doc.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of S.S. No. 2

The S.S. No. 2 due 11.98 partly held at London in Jan 99 has now been completed by the examination of after peak, Engine/Roller space including bunkers (except port side bunkers), decks, masts, spars, rigging, pumps, sluices equipment, and the ranging of the cables.

Repairs due to wear & tear: 1 Beam repaired, 1 bunker stay & fittings renewed. Some cement repaired minor repairs.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Paired or Repaired ...								
Paired or Repaired in place ...								

PRESENT CONDITION OF THE	Stringers	Good	Engine Room Skylights	Good	Boats	Good
Decks						
Caulking of Decks	—	—	Inner Bottom Plating	—	Masts, Yards, &c.	—
Waterways	—	—	State if Tanks now tested	no	Condition, how ascertained	by exam.
Coamings	—	—	Bulkheads	good	(State if wedges removed)	no
Beams & Fastenings	—	—	Ceiling	—	Sails	—
Outside Plating	—	—	Cement or Asphalt (State which.)	Good in Engine Room	Equipment letter	e
Caulking of ditto	—	—	Rudder	not seen	Anchors, No. of	213 15 14
Rivets	good	—	Windlass	good	Cables (State if new ranged)	yes
Breasthooks & Crutches	not seen	—	Have Pumps now been examined and found efficient?	yes	" length (on board)	165 size 19/16
Transoms	good	—	Have Sluice Valves now been examined and found efficient?	yes	" Rule length (per Table 22)	165 size 19/16
Frames	—	—	Have Watertight Doors now been examined and found efficient?	—	Hawsers & Warps	good
Reverse Frames	—	—	Dblng. Plates under Sounding Pipes	—	Standing & Running Rigging	—
Floors	Good	—				
Keelsons	—	—				

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.98," or "to remain as classed and to have record of survey, 1.98, and the notations of 'No. 1-98 and ptnD98, &c.,'"

This vessel appears to be in a good and efficient condition eligible in my opinion to remain as classed and to have record of survey 12.99 ton and notation of S.S. London No. 2-99 as per London Report No. 60883.

Office Fee (if chargeable) per Scale II, Sec. 27	2	Fees applied for,	28/12 18 99	S.A. Nash.
Survey Fee (per Section 28)	£ 1 : 4 : 8	Received by me,	20/1 18 00	L.W. Cooper
Special Damage or Repair Fee (if any) (per Sec. 28)	£ 1 : 8 : 0		SA 14	Surveyor to Lloyd's Register of British & Foreign Shipping.
Travelling Expenses (if chargeable)	£ 3 : 12 : -			
Second Surveyor's Fee (if any)	£ : : -			

Committee's Minute FRI. 29 DEC 1899 ✓

Character assigned 10071 ✓

V. S. No. 2-99

HULL CERTIFICATE WRITTEN. 9/18/00