

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

30 SEP '35

Date of writing Report	Sep 9 1935	When handed in at Local Office	Sep 9 1935	Port of Vancouver BC
No. in Reg. Book.	Survey held at N. Vancouver BC.		Date, First Survey	Aug 5
33577	on the Machinery of the Wooden Steel M.V. CENDROS ex SHEAN		Last Survey	Sep 6 1935
Tonnage	Gross 1420	By whom	Samuel Lewis Lee	When 1920. 7.
Net	181		By whom	R. Beardmore Lee When 1921. 10
Nominal Horse Power	91		(Donkey) 1920.	
No. of Main Boilers	✓	Owners' Address	Port Esmeralda Voyage Mexico	
No. of Donkey Boilers	1	(if not already recorded in Appendix to Register Book.)		
Steam Pressure in Main Boilers	✓			
In Donkey Boilers	100	If Surveyed Afloat or in Dry Dock L.A. N. Van Ship Repair	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	

Last Report No. Port

Particulars of Examination and Repairs (if any) L.M.C.

(Periodical Surveys, when held, must be reported in detail and separately in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " "

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Tested under hydraulic pressure to 135 lb.

State latest date of internal examination of each boiler Aug. 7 1935

UNDERTAKING CASE! OIL ENGINE

Present condition of funnel(s) good

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam? 100 lb

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ , and of the Donkey Boilers? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boiler? Yes

Did the Surveyor examine all the mountings of the Main Boilers? ✓ , and of the Donkey Boiler? Yes

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated? No

Has shaft now been changed? No If so, state reasons. ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated? ✓

State date of examination of Screw Shaft Aug 6 1935 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 16.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Vessel placed on dry dock. All sea connections and discharge opened up and examined. The fastenings of Sea Connections, Stern bush and propeller examined. Screw shaft drawn and examined.

D.B.S.- Donkey boilers opened up, cleaned & examined throughout with all mountings. Tested by water pressure to 135 lb. per sq. inch & found satisfactory. Safety valves adjusted under steam to 100 lb. per sq. inch.

L.M.C.- Main Engines- Examined all cylinders, pistons, covers, piston pins, crank pins & brasses, main bearings & brasses, valve gears & fuel pumps, attached circulating & bilge pumps, valves & connections, & exhaust manifold.

Examined Thrust shaft, collar & bearings, Intermediate

General Observations, Opinion, and Recommendation:- The machinery of this vessel is

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0, II, B&M.S. 0, II, or +L.M.C. 0, II, 140 lb., F.D., &c.)

Eligible in my opinion to remain as Classed with fresh record of +L.M.C. 8. 35. and notation C.L. 8. 35. D.B.S. 8. 35

Survey Fee (per Section 20)	LMC	£ : 65 00	Fees applied for
TS-BS-EE the Molophilin		£ : 45 00	Sep 9 1935
Special Repairs (if any) (per Section 20)		£ : 30 00	
Travelling expenses (if chargeable)		£ : 10 00	Received by me, 19

Committee's Minute

Assigned

+ LMC 9.35 CERTIFICATE WRITTEN
S.P. 35

© 2018 Lloyd's Register Foundation

Port of Vancouver B.C. Continuation of Report No. 4029 dated Sept. 9, 1935. on the

M.V. "CEDROS" ex "SHEAN"

L.M.C. - shaft & bearings, piping and water cooling arrangements & connections.

Starting Air Reservoirs - (3) opened up & examined internally with mountings & connections.

3. air reservoirs tested by water pressure to 550 lbs. per sq. inch & found satisfactory.

Safety valves adjusted to 300 lbs.

Separate Air Compressor. (2 stage) Engine and compressor opened up & examined throughout; also tested.

General service pumps (steam) - opened up & examined throughout with valves & connections & tested.

Donkey Boilers feed pump (steam) 3x2x3 "Worthington" duplex. renewed. Steam cylinders of old pumps fractured by frost.

Oil fuel burning equipment, for Donkey Boilers, examined throughout and tested.

Daily service fuel tanks. examined throughout with connections & tested.

Electric Generators, direct driven and also belt driven from main engine, examined throughout & tested under working conditions with satisfactory results. Examined all wiring & connections, fuses & switch board.

Rebuilds - main engine

New cylinders now fitted to N^os 1-2 & 4.

New heads now fitted to N^os 1-2-3 & 4.

New pistons - do - to N^os 1-2 & 4 also quillon pins.

New piston rings fitted throughout.

Note - cylinders N^os 1-2 & 4 worn oversize.

N^o 4 - crank pin brass re-metalled.

Spare gear examined & found in order.

A satisfactory dock and harbour trial under working and manoeuvring conditions now carried out.



© 2018

Lloyd's Register
Foundation

Made in England

W.B. Bell
Seymour S. Smithson, Lloyds owners
Revised

It is submitted that
this vessel is eligible for
THE RECORD.
Aug. 25.
St. L. G. M.

B.G.
15/9/91



© 2018

Lloyd's Register
Foundation