

of Surveyors

Received from Chief Surveyors

NAME Steel S.S. "CONTE ROSSO" Report Gls. No. 41720

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Survey

When due

✱100 A.1. (Steel) "With freeboard"

2 decks (Steel) & Shelter Deck (steel) & Shade deck (Steel-teaks)  
Cell DB 478' <sup>146t</sup> FPT 88t, APT 96t  
3rd deck (Steel) in holds.

FK, 9 BH to shelter deck, Cem, Lloyd's A & C P, B 327' F 50' on shade deck.

Date of build 2,22

2. 3. 22.

*L. Gls 2/3/22*  
It is concluded <sup>that</sup> the topside plating is doubled at the ends of the erections as approved; that the thickness of the sheerstrake in way of the sidelights has been approved and that 3 hand pumps and 2 downton pumps are fitted as shewn in the plan of pumping arrangements, but the Surveyors should be requested to state if this is so; they should also be requested to state the water capacity of the double bottom tanks in way of the oil fuel bunkers if these may be used for ~~water~~ ballast.

*It is further Concluded that the Consent of the Owners has been obtained to the Alterations from the Rules as required, but the Surveyors should be requested to state if this is so*

*S. L. H.  
10.3.22*



© 2018

Lloyd's Register Foundation