

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

Sld. 35024
 Nwc. 105324
 Hpl. No. 18968

NAME "BRITISH VENTURE" REPORT

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

No. type of Engine Oil Engine 2 S.C.S.A.
 19 3 Cyl. 23 $\frac{5}{8}$ " - 91 $\frac{5}{16}$ "
 MN 534

~~-If-Boilers-fitted-with-forced-draught~~

Tail Shaft. If fitted with a continuous liner Yes

If fitted with an outside gland of approved type No

The torsional vibration characteristics of the main propelling machinery were approved in Secretary's letter of 17.1.47 for a service speed of 108 R.P.M.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * LMC 12.48,
 2 DB 150 lb.



© 2021

18. 1. 49.
 Lloyd's Register
 Foundation

002442-002448-0112