

REPORT ON STEAM RECIPROCATING ENGINE MACHINERY.

Received at London Office 7 JUN 1943

Date of writing Report **20th Apr., 1943** When handed in at Local Office **20th Apr., 1943** Port of **Vancouver, B. C.**

No. in Survey held at **Vancouver, B. C.** Date, First Survey **3rd March, 1943** Last Survey **20th April, 1943**

Reg. Book. --- on the **Steel Single Screw Steamer "FORT DEASE LAKE"** (Number of Visits **24**) Tons {Gross **7125.77**
Net **4247.49**

Built at **Vancouver, B.C.** By whom built **Burrard Dry Dock Co. Ltd.** Yard No. **163** When built **1943**

Engines made at **Montreal, P.Q.** By whom made **Dominion Engineering Wks.** Engine No. **80** When made **1943**

Boilers made at **Vancouver, B.C.** By whom made **Dominion Bridge Co. Ltd.** Boiler No. **399**
401
403 When made **1943**

Registered Horse Power. **229** Owners **Minister of Munitions & Supply of Canada.** Port belonging to ---

Nom. Horse Power as per Rule **504** Is Refrigerating Machinery fitted for cargo purposes. **No** Is Electric Light fitted **Yes**

Trade for which Vessel is intended **General Cargo**

ENGINES, &c.—Description of Engines **Triple Expansion. Superheat to 575° F.** Revs. per minute **80**

Dia of Cylinders **24 1/2" x 37" x 70"** Length of Stroke **48"** No. of Cylinders **3** No. of Cranks **3**

Crank shaft, dia. of journals as per Rule **13.99"** Mid. length breadth --- Thickness parallel to axis **9" & 9 1/2" L.P.**
as fitted **14 1/2"** Crank pin dia. **14-1/4"** Crank webs --- Thickness around eye-hole **(7 1/2" Pin**
(7 3/8" Journal

Intermediate Shafts, diameter as per Rule **13.33"** Thrust shaft, diameter at collars as per Rule **13.99"**
as fitted **13.5"** as fitted **14.25"**

Tube Shafts, diameter as per Rule --- Screw Shaft, diameter as per Rule **14.87"** Is the **tube** shaft fitted with a continuous liner { ---
as fitted --- as fitted **15.25"** as fitted **15.25"** as fitted **15.25"** Is the **screw** shaft fitted with a continuous liner { **Yes**

Bronze Liners, thickness in way of bushes as per Rule **.75"** Thickness between bushes as per Rule **.565"** Is the after end of the liner made watertight in the
as fitted **.78125"** as fitted **.68"** propeller boss **Yes** If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner. **Solid**

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive **Tight fit**

If two liners are fitted, is the shaft lapped or protected between the liners --- Is an approved Oil Gland or other appliance fitted at the after end of the tube
shaft **No** If so, state type --- Length of Bearing in Stern Bush next to and supporting propeller **61"**

Propeller, dia. **18'-6"** Pitch **16'-0"** No. of Blades **4** Material **Bronze** whether Moveable **Solid** Total Developed Surface **117 sq. ft.**

Feed Pumps worked from the Main Engines, No. **None** Diameter --- Stroke --- Can one be overhauled while the other is at work ---

Bilge Pumps worked from the Main Engines, No. **Two** Diameter **4 1/2"** Stroke **26"** Can one be overhauled while the other is at work **Yes**

Feed Pumps (No. and size **Two (10"x7"x24")** Pumps connected to the Main Bilge Line { No. and size **Four (One) 10"x12"x10" (One) 9"x6"x10" Two Rams**
(How driven **Steam Worthington Simplex** Main Bilge Line { How driven **Duplex Steam Duplex Steam M.E.**

Ballast Pumps, No. and size **(One) 10"x12"x10" type.** Lubricating Oil Pumps, including Spare Pump, No. and size **None**

Are two independent means arranged for circulating water through the Oil Cooler --- Suctions, connected to both Main Bilge Pumps and Auxiliary
Bilge Pumps;—In Engine and Boiler Room **1-3" Dia. Port, 1-3" Dia. Star in Blr. Rm., 1-3" Dia. Port, 1-3" Dia. Star** **bd**
In Pump Room **1-2 1/2" Dia. in in Engine Rm., 1-2" Dia. in Thrust Bess.**
In Holds, &c. **1-4" Dia. to P.P., 1-3" Dia. P&S to Nos. 1-2-3-4 & 5**

Holds, **1-4" dia. to A. P.**

Main Water Circulating Pump Direct Bilge Suctions, No. and size **(One) 9"** Independent Power Pump Direct Suctions to the Engine Room Bilges,
No. and size **(One) 5" Dia. Star side** Are all the Bilge Suction Pipes in holds and tunnel well fitted with strum-boxes **Yes**

Are the Bilge Suctions in the Machinery Space led from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges **Yes**

Are all Sea Connections fitted direct on the skin of the ship. **Yes. Main Injection** they fitted with Valves or Cocks **Yes**

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates. **fitted to steel tube through D.B. tank.** Are the Overboard Discharges above or below the deep water line **Below**

Are they each fitted with a Discharge Valve always accessible on the plating of the vessel. **Yes** Are the Blow Off Cocks fitted with a spigot and brass covering plate **Yes**

What Pipes pass through the bunkers **Steel Air Pipes to No. 4 D.B. tanks** How are they protected. **Steel Straps welded across frames,**
Bilge Suctions, **under Limber Boards** **Yes**

What pipes pass through the deep tanks **No. 7 D.B. Air Pipes** Have they been tested as per Rule **Yes**

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times **Yes**

Is the arrangement of Valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or machinery spaces, or from one
compartment to another. **Yes** Is the Shaft Tunnel watertight. **Yes** Is it fitted with a watertight door **No** worked from ---

MAIN BOILERS, &c.—(Letter for record ---) Total Heating Surface of Boilers **7140 sq. ft.**

Which Boilers are fitted with Forced Draft **All Three** Which Boilers are fitted with Superheaters **All Three**

No. and Description of Boilers **3 Single ended multitubular** Working Pressure **220 lbs. per sq. inch.**

IS A REPORT ON MAIN BOILERS NOW FORWARDED? **Yes**

IS A DONKEY BOILER FITTED? **No** If so, is a report now forwarded? ---

Can the donkey boiler be used for domestic purposes only. ---

PLANS. Are approved plans forwarded herewith for Shafting **Approved Plans** Main Boilers --- Auxiliary Boilers --- Donkey Boilers ---
(If not state date of approval) **in U.K.**

Superheaters **Approved Plans** General Pumping Arrangements --- Oil fuel Burning Piping Arrangements ---
in U.K.

SPARE GEAR.

Has the spare gear required by the Rules been supplied **Yes**


State the principal additional spare gear supplied ---

As per list forwarded with Vancouver Report No. 5718 - S.S. "FORT ST. JAMES"

The foregoing is a correct description
Burrard Dry Dock Company, Limited

[Signature]
President

Manufacturer.



4: 5905

During progress of work in shops - - See Montreal Report No. 5821
 Dates of Survey while building {
 Mar. 3, 10, 12, 13, 15, 19, 22, 23, 27, 29, 30, 31.
 During erection on board vessel - - Apr. 1, 2, 5, 9, 10, 13, 14, 15, 16, 17, 19, 20.
 Total No. of visits 24

Dates of Examination of principal parts - Cylinders Slides Covers
 Pistons Piston Rods Connecting rods
 Crank shaft Thrust shaft 5th April, 1943 Intermediate shafts 5th April, 1943
 Tube shaft See Montreal Report No. 5821 Screw shaft 3rd March, 1943 Propeller 3rd March, 1943
 Stern tube 2nd March, 1943 Engine and boiler seatings 10th March, 1943 Engines holding down bolts 2nd April, 1943
 Completion of fitting sea connections 10th March, 1943

Completion of pumping arrangements 9th April, 1943 Boilers fixed 1st April, 1943 Engines tried under steam 13th April, 1943
 Main boiler safety valves adjusted 10th April, 1943 Thickness of adjusting washers P41/64" 25/32" P25/64" 3/4" S.Blr. S 5/8" 300
 Crank shaft material O.H. Steel Lloyd's 3915 H.S. 9-2-43 Thrust shaft material O.H. Steel Lloyd's EER 29-10-42 3506 EER 29-10-42 8974 EER 24-10-42
 Intermediate shafts, material O.H. Steel Lloyd's 1776 EER 29-10-42 3502 EER 29-10-42 9517 EER 29-10-42
 Screw shaft, material O.H. Steel Lloyd's 1776 E.E.R. Steam Pipes, material S.D. Steel Test pressure 660 lbs. Date of Test 5th Apr. 27-1-43

Is an installation fitted for burning oil fuel No Is the flash point of the oil to be used over 150°F. --
 Have the requirements of the Rules for the use of oil as fuel been complied with --
 Is the vessel (not being an oil tanker) fitted for carrying oil as cargo No If so, have the requirements of the Rules been complied with --
 If the notation for Ice Strengthening is desired, state whether the requirements in this respect have been complied with --
 Is this machinery duplicate of a previous case Yes If so, state name of vessel S.S. "FORT ST. JAMES" (Ver. Report No. 5718)

General Remarks (State quality of workmanship, opinions as to class, &c.)
 The machinery of this vessel has been constructed under special survey of the Montreal Surveyors and installed on board under special survey in accordance with the approved plans, New York letters and otherwise in conformity with the Society's Rules. The materials and workmanship are good and the tests required by the Rules have been satisfactorily carried out. The whole installation has been examined and tested under full working conditions on sea trials and afterwards part opened out and examined and found satisfactory. The machinery has also been surveyed during construction and installation on behalf of Wartime Merchant Shipping, Ltd., to ensure that the terms of the specifications have been fully complied with and this work has been satisfactorily carried out.

The machinery of this Vessel is eligible in our opinion to be classed in the Register Book with Notation of *L.M.C. 4,43 Screw Shaft C.L. 3 S.E. Blrs. 220 lbs. per sq. inch F.D.

(This section contains faint, mostly illegible text and markings, possibly bleed-through from the reverse side of the page.)

Montreal fees charged in Montreal Report No. 5821

The amount of Entry Fee ... £	:	:	When applied for,
Special (Ver.) ... £133.00	:	:	20 th Apr. 1943
Donkey Boiler Fee ... £	:	:	When received,
Travelling Expenses (if any) £ 20.00	:	:	19

W.B. Baillie
 Engineer Surveyor to Lloyd's Register of Shipping.

FRI. 11 JUN 1943

Committee's Minute
 Assigned + L.M.C. 4.43
 J.B. C.L.

Certificate to be sent to
 The Surveyors are requested not to write on or below the space for Committee's Minute.

