

EA

18 FEB 1963

Ship's name

"TUNG FENG"

Port

H.Kg

No. 17343

The HONG KONG Surveyors report (11,62) this ship placed in dry dock and due to damage to stranding, the bottom shell plating etc. found extensively damaged. On account of cost repairs were not proceeded with.

It is noted from the Casualty Report that "damage by stranding 9,62 - to be broken up" is recorded against the ship.

IT IS SUBMITTED no further ACTION is necessary.

DM
15.2.63



© 2020

Lloyd's Register
Foundation