

AME

"RYUKIN MARU"

REPORT

Kob.

No. 6658

ing Conditions of Class: SUBJECT to centreline pillaring in No.1 cargo hold being specially examined and dealt with as found necessary by the Special Survey.

ment of Certificate (As before ~~xxxx~~ ~~None~~)

due: SPECIAL SURVEY (C) due 4,60.

of Present Survey: (Afloat and in dry dock)

Docking: Commencement of Special Survey: Wear and tear repairs including deferred item as above: Permanent repairs to damage (two contacts).

Features:

A Drilling Survey was carried out at this time. (Ancient Reply for Approval)

rim Certificate in order (Yes-~~No~~-~~None~~)

utstanding: (~~xxxx~~ ~~any~~ ~~for~~ S.S.)

TO BE EXAMINED INTERNALLY & TESTED:- Tween deck O.F.tank (s.s.).

be completed by:

ndation:

SUBMITTED record of 'DS 4,59' be assigned, without special conditions, the notation of 'SS(Dr) 4,59' being WITHHELD for completion of the Special Survey.

DS 4,59 Without.

IN S.R.L. APPENDIX

No.1 plate (s.s. from aft) in 1st strake below sheer indented.

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded they are in error in stating strength deck plating drilled at frames 60 and 138½ as the original thicknesses tabulated by them do not agree with records in this Office.

S.S. Part Refd.

© 2020

Lloyd's Register  
Foundation

003200-003207-0188