

Received from Chief Engineer Surveyor.....  
 by Chief Engineer Surveyor.....  
 S NAME Tw: Sc: "EMPIRE SHEARWATER" REPORT Gls No. 89407

This vessel was built at Sunderland in 1945 as a transport ferry for the Admiralty, under B.C. Survey. The Main Engines were built under L.R. Survey, the Main Boilers under B.C. Survey, and the installation on the vessel under B.C. Survey. Present Owners desire Classification with this Society.

Plans for this purpose have been examined and approved, the vessel seen in drydock, Screwshafts' Survey held, and the full requirements of L.M.C. carried out.

The Electric Installation has been examined, megger tested and found satisfactory under working conditions.

The vessel appears worthy to be classed:-

+LMC. ES 12.58 M.B.S. 10.58 T.S.10.58 O.G. SPS.10.58

with notations:-

2 Engines, Triple Expansion, <sup>each</sup> 4 cylinders 18½" x 31" x (2) 38½" - 30"  
 l.H.P. 5,500 M.N. 990 2 W.T.B. 225 lbs  
 H.S. 10,650 sq.ft. F.D. O.F.

Note for SRL. Appendix. Surfaces of Main Engine crankpins and journals somewhat corroded.

P.T.O..... /



© 2020

Lloyd's Register  
 Foundation

003245-003251-0180

Received from Chief Engineer Surveyor  
Tw: Sc: "EMPIRE SHEARWATER"  
REPORT

Tw: Sc: "EMPIRE SHEARWATER"

Before this case receives consideration, the attention of the Surveyors should be drawn to the Secretary's letter Eng. dated 3.10.58 and be requested to state whether items 1, 3, 5, 6 and 7 have been complied with, as no mention is made of these items in the Report.

yes  
pls letter 7/1/59  
[Signature]  
9/1/59

[Signature]  
31.12.58



© 2020

Lloyd's Register  
Foundation

Has a Survey also been held on Ship? ...  
If so is the Report sent now, or when will it be sent?

circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Surveyors or in any entry in the Register Book or other publication of the Society, or for any error of judgment, detail or negligence of any of the Committee or any Member thereof.