

10 AUG 1961

Received from Chief Ship Surveyor.....

NAME "ESSO MANCHESTER" REPORT SOU No. 26980

ding Conditions of Class: NONE.

ACTION is DEFERRED for examination in dry dock after grounding.

Appendix. (As before ~~or None~~)

of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to fractured shell plate.

ondation:

SUBJECT to shell plate in 2nd strake below sheer in way of shell connection of transverse bulkhead between Nos.4 & 5 cargo tanks (s.s.) being specially examined and dealt with as necessary next drydocking, but ACTION continue to be DEFERRED for examination in dry dock after grounding.

BJECT.

S.R.L. drydocking (grounding).

S.R.L. APPENDIX.

Shell plates Nos.1 & 2 from fwd. indented. Shell plates Nos.4 & 5 in 1st, 2nd and below sheer (p.s.f) indented.



© 2021 X

Lloyd's Register Foundation

003534-003540-0110