

Received from Chief Ship Surveyor

8 DEC 1959

SHIP NAME "R U T H"

REPORT

Yka.

No. 3027

B

Standing Conditions of Class:

SUBJECT to indented shell plates 1st strake below sheer No.13 (p.s. from fwd) (E.W. and doubled 10,57), G.6 and F.5 & 6 (s.s. from fwd) and H.5 (p.s. from fwd), and fractured shell plate C.2 (p.s.a) (locally doubled 1,59) being specially examined and dealt with as necessary, also to rudder mainpiece (E.W.1,59) being specially examined, next drydocking.

L. Appendix. (As before or None)ure of Present Survey: (Afloat and in dry dock)

Damage repairs (stevedore).

Recommendation:SUBJECT as above.

As Now. Subject

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded the above repairs were tested satisfactorily, but confirmation is desired.

JG
4-12-59

See book Bc.



© 2020

Lloyd's Register
Foundation

003605-003610-0731