

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

28 JAN 1953

Date of writing Report 17/1/53 When handed in at Local Office 21st JAN 1953. Port of GREENOCK
No. in Reg. Book. Survey held at GREENOCK Date. First Survey 25/11/52 Last Survey 30/12 1952 (No. of Visits 4)

On the Machinery of the Wood, Iron or Steel WEATHER OBSERVER

Tonnage { Gross Vessel built at ABERDEEN By whom HALL RUSSELL & CO LTD When -
Net Engines made at ABERDEEN By whom HALL RUSSELL & CO LTD When -
MN Boilers, when made (Main) (Donkey)
Owners AIR MINISTRY Owners' Address
(if not already recorded in Appendix to Register Book.)
No. of Main Boilers 2 Managers Port Voyage
No. of Donkey Boilers -
Steam Pressure in Main Boilers 225 If Surveyed Afloat or in Dry Dock AFLOAT
(State name of Dock.) THE PERCH GREENOCK
in Donkey Boilers

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years elapsed since last survey.	Machinery and Boiler Surveys (including date of N.B., if any)
Classification correct		

Port No. 24787 Port GMR
Reasons of Examination and Repairs (if any) COMPLETION RECLASSIFICATION

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides in the body of the report, should be briefly summarised at the end of the report. State also the dates and by letters respecting this case

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Has a special damage report been made by anyone else? If so, by whom?

Did you personally go inside each Main Boiler separately and make a through examination at this time?

Did you personally go inside each Donkey Boiler separately and make a through examination at this time?

For what reasons? What parts of the Boilers could not be thus thoroughly examined?

By what means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State the nature and extent of internal examination of each boiler. Present condition of funnel(s)

Did you examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Did you examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Did you examine all the manholes, doors, and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did you examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did you examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has the shaft now been drawn and examined? Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft. State the wear down in the

Is electric light and/or power fitted? If so, did the Surveyor examine the generators, motors, switchgear cables and fuses?

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

When referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete

Work done for completion of P.M.C. The following main machinery opened up & examined & found or placed in efficient condition
Main engine H.P. I.P. L.P. & L.P. crossheads & guides top end.
Bearings & pins, connecting rods & bottom end bearings &
ankle pins, eccentric sheaves, straps, & rods
Main steam pipes & main condenser examined under hydraulic
test & found satisfactory
The following auxiliary machinery opened up & examined & found
placed in efficient condition
Distiller pump complete, Fresh water pump & windlass
On completion of survey all main & auxiliary machinery examined &
tested under working conditions & found satisfactory

General Observations, Opinion, and Recommendation: - The machinery of this vessel so far as H.K.C. (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&ES 9,11, & LMC 9,11 or *LMC 140 lb., FD, &c.)
Now seen to be in efficient condition & eligible in my opinion to be submitted for class with record off + L.M.C. 12/52

RECLASSIFICATION BALANCE OF TOTAL 370 00
Survey Fee (per Section 23) FEE INCLUDING ELGE 19
Special Damage or Repair Fee (if any) * + BS
(per Section 23.)
Travelling expenses (if chargeable)

Fees applied for, 19
Received by me, AB Brown
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute MS
Assigned LMC/10.52 BS 6.52
Assign A1 with foreboard "For Government Service" 10.52 Gls subject (Gls 10/179463)
CLASSED BS. * Honor to 12.44 S.S. Gls. - 10.52
S. 10.52 (WEATHER SHIP IN COL. 3)
Littered for oil fuel 11.40 F.P. 150-122

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

003750-003762-0165

