

No. 49463

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

26 NOV 1952

Survey Report 20.11.52. When handed in at Local Office 20.11.52. Port of Glasgow

Survey held at Glasgow. Date. First Survey 1.10.52. Last Survey 16.10.52. (No. of Visits 5)

of the Machinery of the ~~Wood~~ ~~Iron or Steel~~ O.W.S. WEATHER OBSERVER.

Vessel built at Aberdeen By whom Hall, Russell & Co Ltd. When -

Engines made at do By whom do. When -

Boilers, when made (Main) (Donkey) -

Boilers 2 Owners The Air Ministry Owners' Address -

Boilers - Managers - Port - Voyage -

Boilers - If Surveyed Afloat or in Dry Dock Both - In former Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Boilers - Port - Year. Month. -

Boilers - Reclass. Contemp.

Boilers - CHACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Years assigned now expired. Machinery and Boiler Surveys (including date of N.B., if any)

Boilers - Reclass. Contemp.

Boilers - Reexaminations and Repairs (if any) Reclassification.

Insert Character of Ship and Machinery precisely as in the Register Book.

Reexaminations and Repairs (if any) Reclassification.

Part Radios. 33 - - (Electrical + post 49)

Fees applied for 25 NOV 1952 Received by me, 19

Expenses (if chargeable) £ 1:18:2

GLASGOW 25 NOV 1952

Deferred for comp. Mchgy Survey

Ralph M. Richards S. Rowntree Engineer Surveyor to Lloyd's Register of Shipping. C.K. Stevenson

Lloyd's Register Foundation 003750-003762-0170 1/2

Is a Certificate required? If so, to be sent to

Glasgow.

O.W.S. WEATHER OBSERVER.

ELECTRICAL INSTALLATION

Now done: A special survey of the electrical installation carried out. Generators, switchboard, distribution boxes cables and fittings examined and repairs effected.

On completion of repairs generators tested under working conditions, installation examined and insulation resistances measured. All found satisfactory with exception of governing on starboard 50 kW generator engine.

There now remains to be carried out: -

A test on the starboard generator engine governor after repair and adjustment.

R.

Noted
Per Reclassification.

L.L.
23/12/52.

