

(Received at London Office 29 DEC 1955)

29 DEC 1955

No in
Reg. Book. Survey held at Prangemont Date. First ^{last} Survey 12/2/55 Last Survey — 19—
(No. of Visits 1)

32943 on the Machinery of the Wood, Iron or Steel. S. "YEWCRIFT" (No. of Visits 7)

		Year.		Month.					
Tonnage	Gross	827	Vessel built at	Bowling	By whom	Scott & Sons	When	1929	9
	Net	410	Engines made at	bolchester	By whom	Davey, Paulman & Co. (C)	When	1929	9
MN As Per Rule		131	Boilers, when made (Main)	9/1929	(Donkey)				
No. of Main Boilers		156	Owners	John Stewart & Co Shipping Lt.	Owners' Address				
HS " " "			(if not already recorded in Appendix to Register Book.)						
No. of Donkey Boilers		✓	Managers		Port	Glasgow	Voyage		
Steam Pressure—			If Surveyed Afloat or in Dry Dock		Afloat				
in Main Boilers		180 lbs.	(State name of Dock.)			Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).			
in Donkey Boilers		✓							

Last Report No. <u>112856</u>	Port <u>hwc</u>	HULL	MACHINERY
Particulars of Examination and Repairs (if any) <u>SRL Examination</u>		+100A1 8/55	+L.M.C. 10/54
		88 8/41 (20) 10/5	BS 10/54

(Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.....

a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " "

ot, state for what reasons.....What parts of the Boilers could not be thus thoroughly examined?

t special means, in the absence of internal examination, were adopted by the
urveyor to assure himself of the thorough efficiency of those parts of each Boiler?

e latest date of internal examination of each boiler

the Surveyor examine the Safety Valves of the Main Boilers?..... No what pressure were they afterwards adjusted under steam?

the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boiler 2 *Boiler* and of the Donkey Boiler 2

the Sprinkler examine the drain plugs of the Main Boilers?

... ..

....., and of the Donkey Boilers:

the screw shaft now been drawn and examined: Is it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

shaft now been changed? If so, state reasons..... Has the shaft now fitted been previously used? Has it a continuous liner?

approved oil retaining appliance fitted at the after end?.....State date of examination of screw shaft.....State the wear down in the

tern, bush.....Is electric light ~~and~~ or power fitted?.....If so, did the Surveyor examine the generators, motors, switchgear cables and fuses?

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

ine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

SR6 "Metalock" repair to main engine bedplate in way of LP front column now examined and found to continue efficient.

It is recommended that this subject on the Class be now deleted and entered in the list of Endorsements. -

"Main engine bed plate repaired by Metalock"

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

The machinery of this ship, as now seen, is in good condition, capable in my opinion to remain as classed without fresh record and without condition of class regarding main engine & plate.

Survey Fee (per Section 23).....	£ 2 : 2 : -	Fees applied for, 23 Dec 1955
Special Damage or Repair Fee (if any) (per Section 23.).....	£ : : -	
Travelling expenses (if chargeable).....	£ - 10 : -	
		Received by me, 10

Committee's Minute. GLASGOW 28 DEC 1955

Assigned ~~Deferred for BS~~
 It now, without spl cond. (with endorsement.)

Engineer Surveyor to Lloyd's Register of Shipping

Lloyd's Register
Foundation

003816-003823-0192

2000
want
with

ENDORSEMENT (B) MACHIN



12
12

2000
want

ENDORSEMENT (B) MACHIN

[Faint, illegible handwritten text]

[Faint handwritten text]

1000
1000
1000

1000

1000

1000

1000

1000

1000

1000

