

m,8,21.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl T.S.S. "RAZMAK"*

Rpt.

Bel
GmkNo. *9296*
*18307***The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

14 Long
Transverse No. *18731* Depth "d" *16-33'*

Framing: Table No. _____ Description *Bulk angle frames with reversed*

2nd Longitudinal No. *50199* *frame as approved.*

Proportions Length = *13.32*
Depth = _____

Deck Sheerstrake *as approved.*

Revised Rules

The Runley has been completed and the vessel examined in drydock at Belfast and some damage sustained during launching, repaired as necessary.

This vessel appears to have been built in accordance with the *Revised* Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100 A. 1. (Steel)** with freeboard," as recommended. The Summer freeboard of *11 ft 8 1/2 in* from centre of disc to top of statutory deck line at _____ deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

*3 SKs (stl)**Cell D.B 429' 1298t, Tanks at sides of tunnels 436t, F.P.T 57t, A.P.T. 102t.**F.K. 10 B.H, Cen, Lloyds A CP.**P.B 396 F 73'.*

It is concluded the reversed frames ^{as the letter} vertical struts in the double bottom tanks are of bulk angles but the Surveyor should be requested to state if this is so.

Dr 10/2/35

*003971-003979-0104*Any De
Approv
be*72*

ME.

50

FRAME.