

ses where the Surveyor has not made a special damage report he is required to state whether he
services for this purpose and to whom and why they were declined

Society's Freeboard (if as
maintained on Shin and no

COPY

LLOYD'S REGISTER OF SHIPPING,

The Secretary,
LONDON.

BELFAST.

6th May, 1946.

Dear Sir,

We are advised by Messrs. Gregg & Patterson that they have two Steam Trawlers "HOME GUARD" and "GRENADIER" under reconditioning on behalf of the Standard Fishing Co., of Grimsby, and these vessels are to be classed with this Society. The "GRENADIER" was built in 1943 and the "HOME GUARD" in 1944 by Messrs. Cook, Welton & Gemmell Ltd., for the British Admiralty. It is probable that the survey for the Admiralty was carried out by this Society and we would be pleased to be advised if this is so. If not, arrangements will be made for plans to be submitted in due course.

Yours faithfully,

(Sgd).



© 2020

Lloyd's Register
Foundation

004037-004041-0043

Have Watertight Doors now been examined and found

Timbers of Frame at openings ditto

Ditto Ditto at other places ditto

Copper, c
(Sta
When

Boats ...

Masts, ...

Condition

(Stat

Sails ...

Equipme

Anchors.

Chain L

Cables (

„ le