

004093-004100-0031

F.E.

ed by Chief Ship Surveyor ... Received from Chief Ship Surveyor ...

REL'S NAME *Steel S.S. "ABODI-MENDI"* Rpt. *Mat* No. *11059*

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)



Transverse No. *80-08* Depth "d" *23.34*
Framing: Table No. *3* Description *Bull-angle*
Longitudinal No. *31999*
Proportions Length = *11.25*
Depth =

Shelter
Deck Sheerstrake *no approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100-A-1 (Steel) "Shelter Deck"* with freeboard," as recommended. The Summer freeboard of *9'-1 1/2"* from centre of disc to top of statutory deck line at *Shelter* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

1 Dk (Steel) 2 Shelter Dk (Steel)
Cell DB 351' 1170L, APT 100L
FK, Collision Bkt to Shelter Dk, 5 Bkt to Upper Dk, Cam, Shelter A-CR 537' in Shelter Dk
Date of build 5,21

Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.



Lloyd's Register
Foundation