

4 E

29 APR 1955

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VEL'S NAME

Rothgate

REPORT

Mo. No. 112183

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

Vessel in drydock, screws & propeller changed.

Propeller runs taken as a result of which Cos Remch dept recommended in endnt 28/2/55 that a noise board be fitted re varied speed range 238-275 RPM & tachometer marked accordingly.

The two surveyors recommend the propeller now fitted be removed at first opportunity but the reason for this is not understood in the light of above quoted endnt.

It is submitted that this vessel is eligible for THE RECORD 5. 255 with



TORSIONAL  
ENDORSEMENT

SUBJECT

See endnt  
17/4/55  
for

Jan

29. 4. 55.

© 2021

Rothgate

TORSIONAL  
ENDORSEMENT

~~have shoulder pulley advised  
asked for comments & told to withdraw  
cert 31/4/55. Titteri & Police  
board etc to be verified & owners asked to analyse~~

004213-004221-0185