

S.S. "COALFAX"

It is noted that some hatch beams are missing. These beams will require to be replaced, or some such arrangement agreed upon which would satisfy the Lake load line regulations. ✓

~~The marks on the ship's side remain unchanged but the deck line will require to be lowered  $1\frac{1}{2}$  inches to correspond with the top of the stringer plate at side.~~

Life lines to be fitted. ✓

~~Date of last drydocking December 17, 1936.~~ ✓

~~Date of expiry to be inserted on the certificates. (See letter dated March 11.)~~ ✓



© 2020

Lloyd's Register  
Foundation

004394-004404-0048