

Notes of Examination and Repairs (if any)

Repairs, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any.

Date of last Survey and of Periodical Surveys. Class Contem

4 E

Chief Engineer Surveyor _____ Received from Chief Engineer Surveyor _____

NAME "LEELAVATHI" REPORT Mad. No. 283 Cal. 14383

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

This Bassett type trawler was built in India in 1943 and conversion to cargo vessel has now been carried out.

The engine and boiler were made under Special Survey, but not the vessel. Classification is now desired.

Revised arrangements of pumping and electrical installation have been approved and examined.

A complete Classification Survey has been carried out.

IT IS SUBMITTED that this vessel is eligible for the record * ILC MS 11.50, BS 10.51, S(OG) 5.50.

Particulars for Register Book

Triple expansion. 13 1/2" x 23" x 38" - 27" HS 2650 sq.ft. 1 SB 200 lb. F.D. MN 156.



COM

5. 2. 52.



© 2020

Lloyd's Register Foundation

004527-004533-0246

TUES. 12 FEB 1952

8 Minute