

Rpt. 9.
Rpt. 9.

Report of Survey for Repairs, &c., of Engines and Boilers.

No. *Int. Rpt.*

(Received at U.S. Coast Survey Office, New York, July 12, 1885)

(Received at London Office

No. *kncl. Rpt*
d Boilers. *8114*
10 JUN 1951

Date of writing Report.....19..... When handed in at Local Office.....19..... Port ofMontreal, P.Q.
No. in Survey held at.....Kingston, Ont..... Date, First Survey 12th January Last Survey 29th March 1950
Reg. Book 10885.....on the Machinery of the ~~Wooden~~ ~~Iron~~ Steel Screw Steamship "GLENELG" (No. of Visits.....4.....)

Tonnage		Gross.	2099	Vessel built at		Midland, Ont.	By whom		Midland Shipbuilding Co.	When	1923	Year.	Month.
		Net.	1200	Engines made at		Mount Vernon, O.	By whom		C. & G. Cooper Co.	When	1923		
Nominal Horse Power		-		Boilers, when made (Main)		1940			(Donkey)	-			
No. of Main Boilers		2		Owners		Canada Steamship Lines Ltd.	Owners' Address		-				
No. of Donkey Boilers		-		Managers		-	(if not already recorded in Appendix to Register Book.)						
Steam Pressure— in Main Boilers		180		If Surveyed Afloat or in Dry Dock		Afloat, Kingston, Ont.	Port		Midland, Ont.	Voyage	-		
in Donkey Boilers		-		(State name of Dock.)			Particulars of Classification		(which must be inserted)				

Last Report No. Port

Particulars of Examination and Repairs (if any) ... **Change of Boiler.**
(Periodical Surveys, when held, must be reported in detail and *seriatim* in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.....

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside ~~the~~ Main Boiler separately and make a thorough examination at this time?

“ “ Donkey

If this was not done, state for what reasons?.....New Boiler, see First Entry Report.

And what parts of the Boilers could not be thus thoroughly examined?.....None

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of ~~each~~ boiler... 13/3/50

Did the Surveyor examine the Safety Valves of the Main Boiler?.....**Yes**

Did the Surveyor examine the Safety Valves of Donkey Boiler?..... **New Boiler**

...thickness adjusted under steam? 120 lbs. per sq. in.

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers? None

Did the Surveyor examine the drain plugs of the Main Boilers?, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers? New Boiler

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? No Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

Has shaft now been changed?..... If so, state reasons

as the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft State the distance between the two bearings of the screw shaft Is the screw shaft fitted with a bearing at the after end of the shaft?

State date of examination of Screw Shaft..... State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.....

Engine parts, when referred to by numbers, should be counted from forward.

so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?.....

as the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

The two Scotch Boilers were removed from the ship. One three furnace Scotch Boiler ex R.C.N. Corvette "QUESNEL" was installed on boiler stools as shown on Approved Plan. The boiler and its mountings were examined internally and externally and all was found in good condition. New seamless steel main and auxiliary steam piping and main and auxiliary feed pipes were made, tested and fitted. The boiler was hydraulically tested to 330 lbs per sq. in. and found tight. The safety valves were adjusted under steam at 195 lbs. per sq. in. (Calculated on 9-5/8" tailshaft and restricted service) and a satisfactory accumulation test was carried out.

A forced draught fan driven by a single cylinder steam engine with trunking, to the main boiler only was installed this time.

(cont'd)

General Observations, Opinion, and Recommendation:— The Machinery of this ship is in good condition and eligible, in my
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also
any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 1,48, B & M.S. 1,48, +L.M.C. 1,48, or
+LM C 140 lb., F.D., &c.)
CS 1,48,
opinion, to remain as classed with fresh record of survey Boiler Built 10/40, refitted 3/50. msp 3/50, WP 195.
New Donkey Boiler 3/50. WP 120.

Survey Fee (per Section 28)..... \$ 100.00

Special Damage or Repair Fee (if any)..... \$

(per Section 28.)

| travelling expenses (if chargeable) | \$ | 5.00 |

Committee's Minute.....TUES. 27 JUN 1950

Assigned..... As now.

Fees applied for
May 15 1950
Received by me,
19

L. M. Mathen.
Engineer Surveyor to Lloyd's Register of Shipping.

NB + made ¹⁴⁰ ~~50~~, refitted 50
NDB + 150
Blk S. 3, 50 map 3, 50

004591- 004595-010/1/2

10/1/12

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to:

The Stamp Marks of the Boiler were:-

LLOYD'S No. 61

T.P. 388

W.P. 225

1/10/40

R.K.

and the boiler was checked and identified with Dominion Bridge Co. Ltd., Machine,

Qua, Plan of Scotch Marine Boiler No. B746.

One copy of Lloyd's Register Boiler Certificate is attached to this report.

To accommodate the Longer Boiler now installed, the main engines were moved
aft a distance of approximately two feet.

The existing short stub shaft was replaced with a new stub shaft stamped:-

B.C.

T 14444

J.S.

3/3/50.

The existing multicollar thrust block and shaft was removed and a Michell
thrust block and shaft intended for Corvette construction was installed. The shaft
coupling was machined to fit the smaller propeller shaft, and stub shaft coupling.

The new thrust shaft was stamped Lloyd's No. 2786

J.S.

27/9/40.

At this time a new vertical Donkey Boiler was installed on forward starboard
side of the stokehold. This boiler is coupled to the auxiliary steam range
only, through two non - return stop valves. A First Entry Report covering the
new Donkey Boiler is attached to the report. The Boiler safety valves were
adjusted under steam at 120 lbs. per sq. in. and a satisfactory accumulation
test was carried out.

The purpose of installing this Donkey Boiler is to provide steam resources
for pumping and heating when the single Main Boiler is being cleaned.

Z. M. Matheson



© 2020

Lloyd's Register
Foundation
0101/2