

Lloyd's Register of Shipping

Tollbodgaten 27



RECEIVED

Oslo, 17th March 1951.

19 MAR 1951

Ansd.....

Dear Sir,

M.S. "HERBRAND".

Referring to your letter of the 1st instant regarding the above vessel we beg to acquaint you that the owners state that they are not quite clear about the recommendation to renew 30 fathoms of chain cable as stated on the interim certificate.

They state that 30 fathoms of the cable, which the Surveyor at Bremen found doubtful, were tested at Hamburg, and the master has reported that he had been informed that these 30 fathoms were accepted.

As the owners have received no other information regarding any lengths of cable being rejected, they would be glad to be informed whether the above recommendation is correct.

Yours faithfully,
THE SURVEYORS,
Per.

The Secretary,

London.



© 2020

Lloyd's Register
Foundation

004866-004872-0198

CLASSIFICATION

M

14

It is submitted to Surgeons
 La advised that according to the Bureau,
 report (No. 49) the length of ~~the~~ the ham
 cable failed under test at 36 amperes and
 was recommended to be inserted.

BAH.
 22.3.51



© 2020

Lloyd's Register
 Foundation

MS/SM

Yes

1