

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 12903 Survey held at on the Wood, Iron or Steel Sc. K. Montano Date, First Survey Last Survey 19

TONNAGE: GROSS 269 Built at Beverley By whom Cook, Nelson & Gemmell When 1917-9

OWNER DK. 237 Owners Southampton S. F. Co. Owners' Address Managers H. P. Capron Port belonging to Grimsby

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

B=CelldBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined. If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined.

Last Report, No. 18209 Port Grimsby

CHARACTER. (Date of last Survey and of Periodical Surveys)	Years Assigned (now or expired)	Machinery and Boiler Surveys (including date of N.B., if any)
+100 A/10 32		421706, 30
Stm. Trawler		B 811, 32
58 Ply to 3-10, 20		CL 10, 32
58 Ply to 2-30		

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Condition of Decks	State if Tanks now tested	Dbng. Plates under Sounding Pipes	(State if on Roll). When put on, Month Year
Structural Members	Bulkheads	Engine Room Skylights	Boats
Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Plating	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
Sidelights	Rudder	Scuppers	Sails
Stanchions	Steering gear and its connections	Cargo Hatchways	Equipment letter
Windlasses	Windlass	Hatches	Anchors, No. of
Pumps	Have Pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (state if now ranged)
Sluice Valves	Have Sluice Valves now been examined and found efficient?	Caulking ditto	length mean diamr. (on board)
Watertight Doors	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Rule length size
Ventilators	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stimson ditto	Hawser & Warps
Bottom Plating		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
		Timbers of Frame at openings ditto	
		Ditto Ditto at other places ditto	
		Stringers, Clamps & Shelves ditto	
		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and pntND24, &c."

PLANS TRANSFERRED TO SISTER VESSEL LOCK PARK

Survey Fee (per Section 20)	Special Damage or Repair Fee (if any)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for	Received by me
£	£	£	£	19	19

Committee's Minute TUE. 24 OCT 1933 Withdraw class character Assigned Decision of Classing Committee confirmed